

9PL013B00B  
2020-7286

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

9PL013B00B

Document Number Override		Primary Crash Document #	Agency Crash Number	Investigating Officer/Deputy <b>J. HOEGE</b>	
Crash Date <b>07/02/2020</b>		Crash Time <b>09:16 AM</b>	Date Arrived <b>07/02/2020</b>	Time Arrived <b>09:18 AM</b>	
Date Notified <b>07/02/2020</b>		Time Notified <b>09:16 AM</b>	Total Units <b>02</b>	Total Injured <b>02</b>	Total Killed <b>00</b>
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property	<input type="checkbox"/> Active School Zone	School Bus Related <b>NO</b>		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type <b>DT4000 (STANDARD CRASH)</b>		<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

<p>Diagram</p> <p>Not to Scale</p>	<p>Reconstruction By <b>REEDSBURG POLICE DEPARTMENT</b></p>
	<p>Photos By <b>J. HOEGE T. KNUTH</b></p>
	<p>Additional Information <b>NONE, PHOTOS, RECONSTRUCTION</b></p>

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

U1 DID NOT COME TO A COMPLETE STOP AS IT TRAVELED EASTBOUND ON CLARK ST.. U1 STRUCK U2 IN THE LEFT REAR. U1 DRIVEN FROM SCENE WHILE U2 WAS TOWED. ALL INVOLVED DECLINED EMS. SEE REPORT FOR FULL DETAILS.

9PL013B00B

2020-7286

# WISCONSIN MOTOR VEHICLE CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

**Location**

ON CLARK ST 26 FT E OF S JAMES AVE IN THE CITY OF REEDSBURG IN SAUK COUNTY	Latitude <b>43.531453138</b>	Longitude <b>-90.018489944</b>
	X Coordinate <b>256092.984375</b>	Y Coordinate <b>4824261.5</b>
	Structure Type	

**Crash Scene**

First Harmful Event <b>MOTOR VEH IN TRANSPORT</b>	First Harmful Event Location <b>ON ROADWAY</b>	
Manner of Collision <b>03 - FRONT TO REAR</b>	Light Condition <b>DAYLIGHT</b>	
Road Surface Condition(s) <b>DRY</b>	Roadway Factor(s)  <b>NONE</b>	
Environment Factor(s) <b>NONE</b>		
Weather Condition(s) <b>CLEAR</b>		
Animal Type	Relation To Trafficway <b>TRAFFICWAY - ON ROAD</b>	
Crash Classification - Location <b>PUBLIC PROPERTY</b>	Crash Classification - Jurisdiction <b>NO SPECIAL JURISDICTION</b>	
Tribal Land	Access Control <b>PARTIAL CONTROL</b>	Special Study
Within Interchange Area <b>NO</b>	Junction Location <b>INTERSECTION</b>	Intersection Type <b>FOUR-WAY INTERSECTION</b>

**Unit Summary**

<b>UNIT</b>	Unit Status <b>IN TRANSIT</b>	Vehicle Operating As Classification <b>D CLASS</b>		Unit Type <b>AUTOMOBILE</b>	
	Vehicle Type <b>PASSENGER CAR</b>	Operating As Endorsements			
	Total Occs <b>1</b>	Train/Bus # Recorded	Total # Citations Issued <b>1</b>	Total Trailers <b>0</b>	Total HazMat Types <b>0</b>
	Insurance? <b>YES</b>	Direction Of Travel <b>EASTBOUND</b>	<input type="checkbox"/> <b>Pre CrashTire Mark</b>	Speed Limit <b>25</b>	Total Lanes <b>2</b>
	Most Harmful Event: Collision With <b>MOTOR VEH IN TRANSPORT</b>	Special Function <b>NO SPECIAL FUNCTION</b>		Emergency Motor Vehicle Use <b>NOT APPLICABLE</b>	
	Traffic Way <b>TWO-WAY, NOT DIVIDED</b>	Traffic Control <b>STOP SIGN</b>		Traffic Control Inoperative/Missing <b>NO</b>	
	Surface Type <b>BLACKTOP (BITUMINOUS)</b>	Road Curvature <b>STRAIGHT</b>		Road Grade <b>LEVEL</b>	
	Truck Bus or HazMat <b>NO</b>				

<b>UNIT</b>	<b>VEHICLE</b>	<b>Vehicle</b>			
		License Plate Number <b>ACA6177</b>	Plate Type <b>AUT - AUTOMOBILE</b>	St <b>WI</b>	Country of Issuance <b>UNITED STATES</b>
		Vehicle Identification Number <b>1N4BL4BV1KC115178</b>	Make <b>NISSAN</b>	Year <b>2019</b>	Model <b>ALTIMA</b>
		Color <b>BLK - BLACK</b>	Body Style <b>SD - SEDAN</b>		Bus Use
		Initial Contact Point <b>12 - FRONT</b>	Vehicle Damage		
		Extent Of Damage <b>FUNCTIONAL DAMAGE</b>	<b>10 - LEFT SIDE FRONT, 11 - LEFT FRONT CORNER, 12 - FRONT</b>		

9PL013B00B  
2020-7286

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

UNIT VEHICLE	Towed Due To Damage <b>NOT TOWED</b>		Vehicle Removed By <b>OPERATOR</b>		
	What Driver Was Doing <b>GOING STRAIGHT</b>		Vehicle Factors		
	Driver Prior Action Other		<b>NOT APPLICABLE</b>		
	Driver Actions <b>FAILED TO YIELD RIGHT-OF-WAY</b>				
01	01	Owner Name <b>DOERING LEASING CO (414) 461-4100</b>		Owner Address <b>15300 W CAPITOL DR BROOKFIELD, WI 53005 2619, US</b>	
<b>Sequence Of Events</b>					
	01	Event <b>MOTOR VEH IN TRANSPORT</b>			
	02	Event <b>MOTOR VEH IN TRANSPORT</b>			
	03	Event <b>MOTOR VEH IN TRANSPORT</b>			
	04	Event <b>MOTOR VEH IN TRANSPORT</b>			
UNIT	<b>Policy Holder</b>				
	Insurance Company <b>SENTRY-CASUALTY-CO</b>		Organization/Company <b>HOME HEALTH UNITED INC</b>		
UNIT INDIVIDUAL	<b>Individual</b>				
	Driver <b>CAYLA PAULINE ALBRIGHT (608) 408-7860</b>		Citations Issued <b>1</b>	Sex <b>FEMALE</b>	
	Address <b>500 CLARK ST REEDSBURG, WI 53959 , US</b>		Date of Birth <b>12/15/1992</b>	Race <b>WHITE</b>	
			Driver License Number <b>A4161159295504</b> STATE: WISCONSIN COUNTRY: UNITED STATES		
01 001	<b>Safety Equipment</b>		On Duty Crash		
			Safety Equipment		
	Row <b>01 - FRONT ROW</b>	Seat Position <b>07 - LEFT</b>	<b>SHOULDER &amp; LAP BELT</b>		
	Helmet Use		Helmet Compliance		
	Eye Protection		Tint Compliance		
	<b>Injury</b>		Injury Severity <b>NO APPARENT INJURY</b>	Airbag <b>NON DEPLOYED</b>	
	Ejected <b>NOT EJECTED</b>		Ejection Path <b>NOT EJECTED/NOT APPLICABLE</b>	Trapped/Extricated <b>NOT TRAPPED</b>	
Medical Transport <b>NOT TRANSPORTED</b>		EMS Agency Identifier		EMS Run #	
Hospital		Date of Death		Time of Death	
<b>Distracted By</b>		Distracted By Source <b>UNKNOWN</b>			
Distracted By Action <b>UNKNOWN</b>					

9PL013B00B  
2020-7286

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

UNIT	INDIVIDUAL	<b>Non Motorist</b>		Striking Unit #	Location	
		Prior Action				
		Action				
	Action Other				To/From School	
	<b>Drug &amp; Alcohol</b>		Suspected Alcohol Use <b>NO</b>	Suspected Drug Use <b>NO</b>		
	Alcohol Test Given <b>TEST NOT GIVEN</b>		Alcohol Test Type	Alcohol Test Results		
	Drug Test Given <b>TEST NOT GIVEN</b>		Drug Test Type	Drug Test Results		
	Drug Type					
	Individual Condition <b>APPEARED NORMAL</b>					
	<b>Violations</b>					
01	001	UTC Number <b>AL859783</b>	Issue To? <b>001</b>	Statute Number <b>346.18(3)</b>	Description <b>FAIL/YIELD RIGHT/WAY FROM STOP SIGN</b>	

**Unit Summary**

UNIT	02	Unit Status <b>IN TRANSIT</b>		Vehicle Operating As Classification <b>D CLASS</b>		Unit Type <b>AUTOMOBILE</b>			
		Vehicle Type <b>PASSENGER CAR</b>				Operating As Endorsements			
		Total Occs <b>2</b>		Train/Bus # Recorded		Total # Citations Issued <b>0</b>		Total Trailers <b>0</b>	Total HazMat Types <b>0</b>
		Insurance? <b>YES</b>		Direction Of Travel <b>NORTHBOUND</b>		<input type="checkbox"/> <b>Pre Crash Tire Mark</b>		Speed Limit <b>25</b>	Total Lanes <b>2</b>
		Most Harmful Event: Collision With <b>MOTOR VEH IN TRANSPORT</b>				Special Function <b>NO SPECIAL FUNCTION</b>		Emergency Motor Vehicle Use <b>NOT APPLICABLE</b>	
		Traffic Way <b>TWO-WAY, NOT DIVIDED</b>				Traffic Control <b>NO CONTROL</b>		Traffic Control Inoperative/Missing <b>NO</b>	
		Surface Type <b>BLACKTOP (BITUMINOUS)</b>				Road Curvature <b>STRAIGHT</b>		Road Grade <b>LEVEL</b>	
		Truck Bus or HazMat <b>NO</b>							

02	02	<b>Vehicle</b>					
		License Plate Number <b>11723GT</b>		Plate Type <b>IGT - IN GOD WE TRUST</b>		St <b>WI</b>	Country of Issuance <b>UNITED STATES</b>
		Vehicle Identification Number <b>1G11D5SL2FF290592</b>		Make <b>CHEVROLET</b>		Year <b>2015</b>	Model <b>MALIBU</b>
		Color <b>SIL - SILVER (ALUMINUM)</b>		Body Style <b>SD - SEDAN</b>			Bus Use
		Initial Contact Point <b>07 - LEFT REAR CORNER</b>					

9PL013B00B

2020-7286

# WISCONSIN MOTOR VEHICLE CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

UNIT VEHICLE	Vehicle Damage			
	Extent Of Damage <b>DISABLING DAMAGE</b>	<b>07 - LEFT REAR CORNER, 08 - LEFT SIDE REAR</b>		
	Towed Due To Damage <b>TOWED DUE TO DISABLING DAMAGE</b>	Vehicle Removed By		
	What Driver Was Doing <b>GOING STRAIGHT</b>	Vehicle Factors		
UNIT VEHICLE	Driver Prior Action Other	<b>NOT APPLICABLE</b>		
	Driver Actions <b>NO CONTRIBUTING ACTION</b>			
	Owner Name <b>CHRISTIAN EDWARD DALBY</b>	Owner Address <b>247 S JAMES AVE REEDSBURG, WI 53959 , US</b>		
	<b>Sequence Of Events</b>			
UNIT VEHICLE	Event <b>MOTOR VEH IN TRANSPORT</b>			
	Event <b>MOTOR VEH IN TRANSPORT</b>			
	Event <b>MOTOR VEH IN TRANSPORT</b>			
	Event <b>MOTOR VEH IN TRANSPORT</b>			
UNIT VEHICLE	<b>Policy Holder</b>			
	Insurance Company <b>STATE-FARM-GENERAL-INS-CO</b>	Individual <b>CHRISTIAN DALBY</b>		
	<b>Individual</b>			
	Driver <b>CHRISTIAN EDWARD DALBY</b>	Citations Issued <b>0</b>	Sex <b>MALE</b>	
UNIT INDIVIDUAL	Date of Birth <b>10/07/1965</b>	Race		
	Address <b>247 S JAMES AVE REEDSBURG, WI 53959 , US</b>	Driver License Number <b>D4101056536703 STATE: WISCONSIN COUNTRY: UNITED STATES</b>		
	<b>Safety Equipment</b>			
	On Duty Crash	Safety Equipment		
UNIT INDIVIDUAL	Row <b>01 - FRONT ROW</b>	Seat Position <b>07 - LEFT</b>	<b>SHOULDER &amp; LAP BELT</b>	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	UNIT INDIVIDUAL	<b>Injury</b>	Injury Severity <b>POSSIBLE INJURY</b>	Airbag <b>DEPLOYED-SIDE</b>
Ejected <b>NOT EJECTED</b>		Ejection Path <b>NOT EJECTED/NOT APPLICABLE</b>	Trapped/Extricated <b>NOT TRAPPED</b>	
Medical Transport <b>NOT TRANSPORTED</b>		EMS Agency Identifier	EMS Run #	
Hospital		Date of Death	Time of Death	

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

UNIT	<b>Distracted By</b>		Distracted By Source <b>NOT APPLICABLE (NOT DISTRACTED)</b>	
	Distracted By Action <b>NOT DISTRACTED</b>			
	<b>Non Motorist</b>	Striking Unit #	Location	
	Prior Action			
	Action			
	Action Other		To/From School	
	<b>Drug &amp; Alcohol</b>	Suspected Alcohol Use <b>NO</b>	Suspected Drug Use <b>NO</b>	
	Alcohol Test Given <b>TEST NOT GIVEN</b>	Alcohol Test Type		Alcohol Test Results
	Drug Test Given <b>TEST NOT GIVEN</b>	Drug Test Type	Drug Test Results	
	Drug Type			
Individual Condition <b>APPEARED NORMAL</b>				
UNIT	<b>Individual</b>			
	Passenger <b>LORI MARIE DALBY</b>		Citations Issued <b>0</b>	Sex <b>FEMALE</b>
			Date of Birth <b>04/10/1974</b>	Race <b>WHITE</b>
	Address <b>247 S JAMES AVE REEDSBURG, WI 53959 , US</b>		Driver License Number <b>D4105337463009</b> STATE: WISCONSIN COUNTRY: UNITED STATES	
	<b>Safety Equipment</b>	On Duty Crash	Safety Equipment	
	Row <b>01 - FRONT ROW</b>	Seat Position <b>09 - RIGHT</b>	<b>SHOULDER &amp; LAP BELT</b>	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	<b>Injury</b>	Injury Severity <b>POSSIBLE INJURY</b>	Airbag <b>DEPLOYED-CURTAIN</b>	
	Ejected <b>NOT EJECTED</b>	Ejection Path <b>NOT EJECTED/NOT APPLICABLE</b>		Trapped/Extricated <b>NOT TRAPPED</b>
Medical Transport <b>NOT TRANSPORTED</b>		EMS Agency Identifier	EMS Run #	
Hospital		Date of Death	Time of Death	
<b>Distracted By</b>	Distracted By Source			

# WISCONSIN MOTOR VEHICLE CRASH REPORT

<b>UNIT</b>	Distracted By Action				
	<b>Non Motorist</b>	Striking Unit #	Location		
		Prior Action			
	<b>INDIVIDUAL</b>	Action			
		Action Other		To/From School	
		<b>Drug &amp; Alcohol</b>	Suspected Alcohol Use <b>NO</b>	Suspected Drug Use <b>NO</b>	
			Alcohol Test Given <b>TEST NOT GIVEN</b>	Alcohol Test Type	Alcohol Test Results
		Drug Test Given <b>TEST NOT GIVEN</b>	Drug Test Type	Drug Test Results	
	Drug Type				
	Individual Condition <b>APPEARED NORMAL</b>				
<b>02</b>	<b>003</b>				