

9PL015S28D
R21-10709

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

9PL015S28D

Document Number Override	Primary Crash Document #	Agency Crash Number	Investigating Officer/Deputy K. YEAGER		
Crash Date 10/04/2021	Crash Time 10:35 AM	Date Arrived 10/04/2021	Time Arrived 10:46 AM		
Date Notified 10/04/2021	Time Notified 10:38 AM	Total Units 02	Total Injured 00	Total Killed 00	
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property	<input type="checkbox"/> Active School Zone	School Bus Related NO	Tags		
<input type="checkbox"/> Reportable	Crash Type PRIVATE PROPERTY/PARKING LOT	<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash		

Description

Diagram	Reconstruction By
	Photos By K. YEAGER #148
	Additional Information PHOTOS

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT ONE WAS BACKING UP OUT OF A PARKING STALL IN THE VIKING VILLAGE GROCERY STORE PARKING LOT. UNIT TWO WAS TRAVELING NORTHBOUND THROUGH THE PARKING LOT LOOKING FOR A PARKING SPOT WHEN UNIT ONE BACK UP INTO UNIT TWO. UNIT ONE STATED THAT THEY DID NOT SEE UNIT TWO UNTIL IT WAS TOO LATE AND THEY HAD ALREADY COLLIDED. UNIT TWO ALSO STATED THAT THEY DID NOT SEE UNIT ONE BACKING UP AND JUST FELT THE IMPACT. INFORMATION DOCUMENTED. THIS IS ALL THE INFORMATION I HAVE AT THIS TIME.

9PL015S28D
R21-10709

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

Location

PARKING LOT VIKING DR LOT 150 (OTHER 150) IN THE CITY OF REEDSBURG IN SAUK COUNTY	Latitude 43.534634345	Longitude -89.983379596
	X Coordinate 258942.859375	Y Coordinate 4824512.5
	Structure Type OTHER	

Crash Scene

First Harmful Event MOTOR VEH IN TRANSPORT	First Harmful Event Location OFF ROADWAY, LOCATION UNKNOWN	
Manner of Collision 05 - REAR TO SIDE	Light Condition DAYLIGHT	
Road Surface Condition(s) DRY	Roadway Factor(s) NONE	
Environment Factor(s) NONE		
Weather Condition(s) CLOUDY		
Animal Type	Relation To Trafficway NON TRAFFICWAY - PARKING LOT	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 2	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0
	Insurance? YES	Direction Of Travel NOT ON ROADWAY	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 05	Total Lanes 0
	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way PARKING LOT OR PRIVATE PROPERTY	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO				

Vehicle

UNIT	VEHICLE	License Plate Number 608YHY	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
		Vehicle Identification Number 1G1AT18H497266260	Make CHEVROLET	Year 2009	Model COBALT	
		Color SIL - SILVER (ALUMINUM)	Body Style CP - COUPE		Bus Use	
		Initial Contact Point 06 - REAR	Vehicle Damage			
		Extent Of Damage MINOR DAMAGE	06 - REAR			



9PL015S28D
R21-10709

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

UNIT	Towed Due To Damage NOT TOWED		Vehicle Removed By OPERATOR		
	What Driver Was Doing BACKING		Vehicle Factors		
	Driver Prior Action Other		NOT APPLICABLE		
	Driver Actions LOOKED BUT DID NOT SEE				
01	01	Owner Name CHETT ALLYN FREDRICKSON (608) 415-8453		Owner Address 104 SCARLET CT REEDSBURG, WI 53959 , US	
		Sequence Of Events			
UNIT	01	Event MOTOR VEH IN TRANSPORT			
		Event MOTOR VEH IN TRANSPORT			
		Event			
		Event			
UNIT	01	Policy Holder			
		Insurance Company PROGRESSIVE-CASUALTY-INS-CO	Individual CHETT FREDRICKSON		
UNIT	001	Individual			
		Driver CHETT ALLYN FREDRICKSON (608) 415-8453	Citations Issued 0	Sex MALE	
			Date of Birth 10/20/1994	Race WHITE	
		Address 104 SCARLET CT REEDSBURG, WI 53959 , US	Driver License Number F6361019438008 STATE: WISCONSIN COUNTRY: UNITED STATES		
01	001	Safety Equipment		On Duty Crash	
				Safety Equipment	
		Row 01 - FRONT ROW	Seat Position	SHOULDER & LAP BELT	
		Helmet Use		Helmet Compliance	
		Eye Protection		Tint Compliance	
		Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED	
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #	
Hospital		Date of Death		Time of Death	
Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)			
Distracted By Action		NOT DISTRACTED			

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	INDIVIDUAL	Non Motorist		Striking Unit #	Location		
		Prior Action					
		Action					
		Action Other				To/From School	
		Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO		
		Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type	Alcohol Test Results		
		Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results		
		Drug Type					
		Individual Condition APPEARED NORMAL					
		UNIT	INDIVIDUAL	Individual			
Passenger DANIELLE JANE ANDERSON				Citations Issued 0	Sex FEMALE		
				Date of Birth 11/22/1993	Race WHITE		
Address 104 SCARLET CT REEDSBURG, WI 53959 , US				Driver License Number A5361709392202 STATE: WISCONSIN COUNTRY: UNITED STATES			
Safety Equipment				On Duty Crash	Safety Equipment		
Row 01 - FRONT ROW	Seat Position 09 - RIGHT			SHOULDER & LAP BELT			
Helmet Use				Helmet Compliance			
Eye Protection				Tint Compliance			
UNIT	INDIVIDUAL			Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED
				Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED
		Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #		
		Hospital		Date of Death	Time of Death		
		Distracted By		Distracted By Source			
		Distracted By Action					
		Non Motorist		Striking Unit #	Location		

UNIT	INDIVIDUAL	Prior Action				
		Action				
		Action Other		To/From School		
	01	002	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO
			Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type	Alcohol Test Results
			Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results
			Drug Type			
			Individual Condition APPEARED NORMAL			

Unit Summary

UNIT	02	Unit Status IN TRANSIT		Vehicle Operating As Classification D CLASS		Unit Type TRUCK	
		Vehicle Type UTILITY TRUCK/PICKUP TRUCK				Operating As Endorsements	
		Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0	
		Insurance? YES	Direction Of Travel NOT ON ROADWAY	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 05	Total Lanes 0	
		Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
		Traffic Way PARKING LOT OR PRIVATE PROPERTY		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
		Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT		Road Grade LEVEL	
		Truck Bus or HazMat NO					

Vehicle

UNIT	VEHICLE	02	License Plate Number HF7145		Plate Type LTK - LIGHT TRUCK	St WI	Country of Issuance UNITED STATES		
			Vehicle Identification Number 3GCUKSEC7FG175070		Make CHEVROLET	Year 2015	Model SILVERADO		
			Color WHI - WHITE		Body Style PK - PICKUP		Bus Use		
			Initial Contact Point 03 - RIGHT SIDE MIDDLE		Vehicle Damage 03 - RIGHT SIDE MIDDLE				
			Extent Of Damage MINOR DAMAGE						
			Towed Due To Damage NOT TOWED		Vehicle Removed By OPERATOR				
			What Driver Was Doing GOING STRAIGHT						

9PL015S28D
R21-10709

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

UNIT VEHICLE	Driver Prior Action Other		Vehicle Factors	
			NOT APPLICABLE	
	Driver Actions NO CONTRIBUTING ACTION			
02	Owner Name JEFFREY MICHAEL SCHARA		Owner Address E7509 HWY PF NORTH FREEDOM, WI 53951 , US	
	Sequence Of Events			
01	Event MOTOR VEH IN TRANSPORT			
02	Event MOTOR VEH IN TRANSPORT			
03	Event			
04	Event			
UNIT	Policy Holder			
	Insurance Company STATE-FARM-MUTUAL-AUTOMOBILE-INS-CO		Individual JEFFREY SCHARA	
UNIT INDIVIDUAL	Individual			
	Driver JEFFREY MICHAEL SCHARA		Citations Issued 0	Sex MALE
			Date of Birth 05/01/1962	Race WHITE
	Address E7509 HWY PF NORTH FREEDOM, WI 53951 , US		Driver License Number S6004336216108 STATE: WISCONSIN COUNTRY: UNITED STATES	
02 003	Safety Equipment		On Duty Crash	
			Safety Equipment	
	Row 01 - FRONT ROW	Seat Position 07 - LEFT	SHOULDER & LAP BELT	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	Injury	Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED	
	Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED
Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #	
Hospital		Date of Death	Time of Death	
Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)		
Distracted By Action NOT DISTRACTED				
Non Motorist		Striking Unit #	Location	

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	INDIVIDUAL		
	Prior Action		
	Action		
	Action Other		To/From School
	Drug & Alcohol		
	Suspected Alcohol Use NO		Suspected Drug Use NO
	Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results
	Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results
	Drug Type		
	Individual Condition APPEARED NORMAL		