

9PL015S28F  
R21-10851

# WISCONSIN MOTOR VEHICLE CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

9PL015S28F

Document Number Override	Primary Crash Document #	Agency Crash Number	Investigating Officer/Deputy <b>T. KNUTH</b>		
Crash Date <b>10/08/2021</b>	Crash Time <b>09:44 AM</b>	Date Arrived <b>10/08/2021</b>	Time Arrived <b>09:52 AM</b>		
Date Notified <b>10/08/2021</b>	Time Notified <b>09:44 AM</b>	Total Units <b>02</b>	Total Injured <b>00</b>	Total Killed <b>00</b>	
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone	<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property	<input type="checkbox"/> Active School Zone	School Bus Related <b>NO</b>	Tags		
<input type="checkbox"/> Reportable	Crash Type <b>PRIVATE PROPERTY/PARKING LOT</b>	<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash		

## Description

Diagram	Reconstruction By
	Photos By <b>T. KNUTH #130</b>
	Additional Information <b>PHOTOS</b>

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 2 WAS STOPPED IN THE PARKING LOT GETTING DIRECTIONS. UNIT 1 PARKED LEGALLY IN A PARKING STALL AND UNIT 2 BACKED UP NOT KNOWING UNIT 1 WAS PARKED BEHIND THEM. UNIT 2 STRUCK UNIT 1. UNIT 1 SUSTAINED MINOR DAMAGE TO THE DRIVER'S DOOR AND UNIT 2 SUSTAINED NO DAMAGE. NOTHING FURTHER.

9PL015S28F  
R21-10851

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

Location

<b>PARKING LOT</b> <b>MAIN ST/ STH23 EB LOT 1625</b> <b>(HOUSE/BUILDING 1625)</b>  <b>IN THE CITY OF REEDSBURG</b> <b>IN SAUK COUNTY</b>	Latitude <b>43.532894135</b>	Longitude <b>-89.985404968</b>
	X Coordinate <b>258772.265625</b>	Y Coordinate <b>4824325</b>
	Structure Type <b>HOUSE/BUILDING</b>	

Crash Scene

First Harmful Event <b>PARKED MOTOR VEHICLE</b>	First Harmful Event Location <b>ON ROADWAY</b>	
Manner of Collision <b>05 - REAR TO SIDE</b>	Light Condition <b>DAYLIGHT</b>	
Road Surface Condition(s) <b>DRY</b>	Roadway Factor(s)  <b>NONE</b>	
Environment Factor(s) <b>NONE</b>		
Weather Condition(s) <b>CLEAR</b>		
Animal Type	Relation To Trafficway <b>NON TRAFFICWAY - PARKING LOT</b>	
Crash Classification - Location	Crash Classification - Jurisdiction <b>NO SPECIAL JURISDICTION</b>	
Tribal Land	Access Control <b>NO CONTROL</b>	Special Study
Within Interchange Area <b>NO</b>	Junction Location <b>NON-JUNCTION</b>	Intersection Type <b>NOT AN INTERSECTION</b>

Unit Summary

<b>UNIT</b>	Unit Status <b>LEGALLY PARKED</b>	Vehicle Operating As Classification <b>D CLASS</b>		Unit Type <b>AUTOMOBILE</b>		
	Vehicle Type <b>PASSENGER CAR</b>			Operating As Endorsements		
	Total Occs <b>0</b>	Train/Bus # Recorded	Total # Citations Issued <b>0</b>	Total Trailers <b>0</b>	Total HazMat Types <b>0</b>	
	Insurance? <b>YES</b>	Direction Of Travel <b>NOT ON ROADWAY</b>	<input type="checkbox"/> <b>Pre Crash Tire Mark</b>	Speed Limit <b>N/A</b>	Total Lanes <b>0</b>	
	Most Harmful Event: Collision With <b>MOTOR VEH IN TRANSPORT</b>		Special Function <b>NO SPECIAL FUNCTION</b>		Emergency Motor Vehicle Use <b>NOT APPLICABLE</b>	
	Traffic Way <b>PARKING LOT OR PRIVATE PROPERTY</b>		Traffic Control <b>NO CONTROL</b>		Traffic Control Inoperative/Missing <b>NO</b>	
	Surface Type <b>BLACKTOP (BITUMINOUS)</b>		Road Curvature <b>STRAIGHT</b>		Road Grade <b>LEVEL</b>	
	Truck Bus or HazMat <b>NO</b>					

Vehicle

<b>VEHICLE</b>	License Plate Number <b>800UDJ</b>	Plate Type <b>AUT - AUTOMOBILE</b>	St <b>WI</b>	Country of Issuance <b>UNITED STATES</b>	
	Vehicle Identification Number <b>2G1WT58K479257286</b>	Make <b>CHEVROLET</b>	Year <b>2007</b>	Model <b>IMPALA LT</b>	
	Color <b>RED - RED</b>	Body Style <b>4D - 4DR</b>		Bus Use	
	Initial Contact Point <b>09 - LEFT SIDE MIDDLE</b>	Vehicle Damage <b>09 - LEFT SIDE MIDDLE</b>			
	Extent Of Damage <b>MINOR DAMAGE</b>				



9PL015S28F  
R21-10851

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

UNIT VEHICLE	Towed Due To Damage <b>NOT TOWED</b>	Vehicle Removed By <b>OWNER</b>
	What Driver Was Doing <b>LEGALLY PARKED</b>	Vehicle Factors
	Driver Prior Action Other	<b>NOT APPLICABLE</b>
	Driver Actions <b>NO CONTRIBUTING ACTION</b>	
01	Owner Name <b>SUSAN LYNNE JENSEN (608) 985-7820</b>	Owner Address <b>411 FURNACE ST IRONTON, WI 53941 , US</b>
	<b>Sequence Of Events</b>	
01 02 03 04	Event <b>MOTOR VEH IN TRANSPORT</b>	
	Event	
	Event	
	Event	
UNIT	<b>Policy Holder</b>	
	Insurance Company <b>AUTO-OWNERS-INS-CO</b>	Individual <b>SUSAN JENSEN</b>

**Unit Summary**

UNIT 02	Unit Status <b>IN TRANSIT</b>	Vehicle Operating As Classification <b>D CLASS</b>	Unit Type <b>TRUCK</b>		
	Vehicle Type <b>UTILITY TRUCK/PICKUP TRUCK</b>		Operating As Endorsements		
	Total Occs <b>2</b>	Train/Bus # Recorded	Total # Citations Issued <b>0</b>	Total Trailers <b>0</b>	Total HazMat Types <b>0</b>
	Insurance? <b>YES</b>	Direction Of Travel <b>WESTBOUND</b>	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit <b>N/A</b>	Total Lanes <b>0</b>
	Most Harmful Event: Collision With <b>PARKED MOTOR VEHICLE</b>		Special Function <b>NO SPECIAL FUNCTION</b>	Emergency Motor Vehicle Use	
	Traffic Way <b>PARKING LOT OR PRIVATE PROPERTY</b>		Traffic Control <b>NO CONTROL</b>	Traffic Control Inoperative/Missing <b>NO</b>	
	Surface Type <b>BLACKTOP (BITUMINOUS)</b>		Road Curvature <b>STRAIGHT</b>	Road Grade <b>LEVEL</b>	
	Truck Bus or HazMat <b>NO</b>				

**Vehicle**

UNIT VEHICLE 02	License Plate Number <b>FAA180</b>	Plate Type <b>LTK - LIGHT TRUCK</b>	St <b>MN</b>	Country of Issuance <b>UNITED STATES</b>
	Vehicle Identification Number <b>1GCRYGED7LZ330979</b>	Make <b>CHEVROLET</b>	Year <b>2020</b>	Model <b>SILVERADO</b>
	Color <b>SIL - SILVER (ALUMINUM)</b>	Body Style <b>PK - PICKUP</b>	Bus Use	
	Initial Contact Point <b>06 - REAR</b>	Vehicle Damage <b>00 - NO DAMAGE</b>		
	Extent Of Damage <b>NO DAMAGE</b>			

9PL015S28F  
R21-10851

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

UNIT	Towed Due To Damage <b>NOT TOWED</b>		Vehicle Removed By <b>OPERATOR</b>	
	What Driver Was Doing <b>BACKING</b>		Vehicle Factors	
	Driver Prior Action Other		<b>NOT APPLICABLE</b>	
	Driver Actions <b>UNSAFE BACKING</b>			
02	Owner Name <b>DUANE GERALD AUSMUS (218) 647-8318</b>		Owner Address <b>21991 AUNE CT NE KELLIHER, MN 56650 3234, US</b>	
	<b>Sequence Of Events</b>			
01	Event <b>PARKED MOTOR VEHICLE</b>			
	Event			
	Event			
	Event			
02	<b>Policy Holder</b>			
	Insurance Company <b>USAA-CASUALTY-INS-CO</b>		Individual <b>DUANE AUSMUS</b>	
	<b>Individual</b>			
	Driver <b>DUANE GERALD AUSMUS (218) 647-8318</b>		Citations Issued <b>0</b>	Sex <b>MALE</b>
Date of Birth <b>07/15/1939</b>		Race <b>WHITE</b>		
Address <b>21991 AUNE CT NE KELLIHER, MN 56650 3234, US</b>		Driver License Number <b>G087085740015 STATE: MINNESOTA COUNTRY: UNITED STATES</b>		
03	<b>Safety Equipment</b>		On Duty Crash	
	Safety Equipment			
	Row <b>01 - FRONT ROW</b>	Seat Position <b>07 - LEFT</b>		
	Helmet Use		Helmet Compliance	
Eye Protection		Tint Compliance		
04	<b>Injury</b>		Injury Severity <b>NO APPARENT INJURY</b>	
	Airbag			
	Ejected	Ejection Path	Trapped/Extricated	
	Medical Transport <b>NOT TRANSPORTED</b>		EMS Agency Identifier	EMS Run #
Hospital		Date of Death	Time of Death	
001	<b>Distracted By</b>		Distracted By Source	
	Distracted By Action			

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

UNIT	INDIVIDUAL	<b>Non Motorist</b>		Striking Unit #	Location		
		Prior Action					
		Action					
		Action Other				To/From School	
		<b>Drug &amp; Alcohol</b>		Suspected Alcohol Use <b>NO</b>	Suspected Drug Use <b>NO</b>		
		Alcohol Test Given <b>TEST NOT GIVEN</b>		Alcohol Test Type		Alcohol Test Results	
		Drug Test Given <b>TEST NOT GIVEN</b>		Drug Test Type		Drug Test Results	
		Drug Type					
		Individual Condition <b>APPEARED NORMAL</b>					
		UNIT	INDIVIDUAL	<b>Individual</b>			
Individual				Citations Issued	Sex		
				Date of Birth	Race		
Address , ,				Driver License Number			
<b>Safety Equipment</b>				On Duty Crash	Safety Equipment		
Row	Seat Position						
Helmet Use				Helmet Compliance			
Eye Protection				Tint Compliance			
UNIT	INDIVIDUAL			<b>Injury</b>		Injury Severity	Airbag
				Ejected	Ejection Path		Trapped/Extricated
		Medical Transport		EMS Agency Identifier		EMS Run #	
		Hospital		Date of Death		Time of Death	
		<b>Distracted By</b>		Distracted By Source			
		Distracted By Action					
		<b>Non Motorist</b>		Striking Unit #	Location		

UNIT	Prior Action			
	Action			
	Action Other		To/From School	
	<b>Drug &amp; Alcohol</b>	Suspected Alcohol Use	Suspected Drug Use	
		Alcohol Test Given	Alcohol Test Type	Alcohol Test Results
		Drug Test Given	Drug Test Type	Drug Test Results
		Drug Type		
	02	002	Individual Condition	