

9PL010TWTF

Document Number Override		Primary Crash Document #		Agency Crash Number		Investigating Officer/Deputy A. REITHMEYER	
Crash Date 11/07/2021		Crash Time 08:22 PM		Date Arrived 11/07/2021		Time Arrived 08:28 PM	
Date Notified 11/07/2021		Time Notified 08:23 PM		Total Units 02		Total Injured 01	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure		<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)				<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

Diagram		Reconstruction By	
<p style="text-align: center;">N. Dewey Ave.</p>		Photos By A. REITHMEYER	
		Additional Information NONE, PHOTOS	

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS LEGALLY PARKED UP AGAINST THE CURB IN THE 1800 BLOCK OF N. DEWEY AVE. FACING SOUTHBOUND. UNIT 2 WAS OPERATING SOUTH BOUND ON N. DEWEY AVE. AND STRUCK THE REAR DRIVER SIDE END OF VEHICLE 1. A WITNESS DESCRIBED SEEING UNIT 2 DRIVING WAY TOO FAST AND SWERVING IN THE ROADWAY. THE WITNESS STATED SHE OBSERVED UNIT 2 OPERATING APPROXIMATELY 40 MILES PER HOUR AND SWERVING INTO ONCOMING TRAFFIC. THE WITNESS WENT ON TO SAY THAT UNIT 2 OVER CORRECTED TO THE RIGHT AND STRUCK UNIT 1. UNIT 2 COULD NOT PROVIDE ANY DETAILS WITH WHAT HAPPENED BECAUSE SHE STATED SHE BLACKED OUT.

Location

ON 1825 N DEWEY AVE 282 FT S OF 19TH ST (HOUSE/BUILDING 1825) IN THE CITY OF REEDSBURG IN SAUK COUNTY	Latitude 43.547594534	Longitude -89.994584377
	X Coordinate 258089.34375	Y Coordinate 4825984.5
	Structure Type HOUSE/BUILDING	

Crash Scene

First Harmful Event MOTOR VEH IN TRANSPORT	First Harmful Event Location SHOULDER RIGHT	
Manner of Collision 07 - SIDESWIPE/SAME DIRECTION	Light Condition DARK/LIGHTED	
Road Surface Condition(s) DRY	Roadway Factor(s) NONE	
Environment Factor(s) NONE		
Weather Condition(s) CLEAR		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT	Unit Status LEGALLY PARKED	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 0	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0
	Insurance? NO	Direction Of Travel SOUTHBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 25	Total Lanes 2
	Most Harmful Event: Collision With PARKED MOTOR VEHICLE	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO				

Vehicle

UNIT	VEHICLE	License Plate Number AFG2496	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
		Vehicle Identification Number 1HGFA16878L102417	Make HONDA	Year 2008	Model CIVIC	
		Color BLK - BLACK	Body Style SD - SEDAN		Bus Use	
		Initial Contact Point 07 - LEFT REAR CORNER	Vehicle Damage 07 - LEFT REAR CORNER, 08 - LEFT SIDE REAR, 09 - LEFT SIDE MIDDLE, 10 - LEFT SIDE FRONT, 11 - LEFT FRONT CORNER			
		Extent Of Damage DISABLING DAMAGE				



WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	VEHICLE	Towed Due To Damage NOT TOWED	Vehicle Removed By
		What Driver Was Doing LEGALLY PARKED	Vehicle Factors
		Driver Prior Action Other	NOT APPLICABLE
		Driver Actions NO CONTRIBUTING ACTION	
01	01	Owner Name ZANAEL PAO AGUIRREZ	Owner Address 4836 CUBA VALLEY RD DEFOREST, WI 53532 , US
Sequence Of Events			
01	01	Event PARKED MOTOR VEHICLE	
02	02	Event	
03	03	Event	
04	04	Event	

Unit Summary

UNIT	02	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS	Unit Type AUTOMOBILE		
		Vehicle Type (SPORT) UTILITY VEHICLE	Operating As Endorsements			
		Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 2	Total Trailers 0	Total HazMat Types 0
		Insurance? NO	Direction Of Travel SOUTHBOUND	<input type="checkbox"/> Pre CrashTire Mark	Speed Limit 25	Total Lanes 2
		Most Harmful Event: Collision With PARKED MOTOR VEHICLE	Special Function NO SPECIAL FUNCTION	Emergency Motor Vehicle Use NOT APPLICABLE		
		Traffic Way TWO-WAY, NOT DIVIDED	Traffic Control NO CONTROL	Traffic Control Inoperative/Missing NO		
		Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT	Road Grade LEVEL		
		Truck Bus or HazMat NO				

Vehicle

UNIT	VEHICLE	02	02	License Plate Number AGN3119	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
		02	02	Vehicle Identification Number JHLRD77434C055319	Make HONDA	Year 2004	Model CR-V LX	
		02	02	Color SIL - SILVER (ALUMINUM)	Body Style LL - CARRYALL	Bus Use		
		02	02	Initial Contact Point 01 - RIGHT FRONT CORNER	Vehicle Damage 01 - RIGHT FRONT CORNER, 02 - RIGHT SIDE FRONT, 12 - FRONT			
		02	02	Extent Of Damage DISABLING DAMAGE				
		02	02	Towed Due To Damage TOWED DUE TO DISABLING DAMAGE	Vehicle Removed By KIT CONRAD			
		02	02	What Driver Was Doing GOING STRAIGHT				

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT VEHICLE	Driver Prior Action Other		Vehicle Factors NOT APPLICABLE	
	Driver Actions EXCEED SPEED LIMIT, FAILED TO KEEP IN DESIGNATED LANE			
	Owner Name EDEN MARIE HARDING		Owner Address 220 PILGRIM DR WISCONSIN DELLS, WI 53965 , US	
UNIT 02	Sequence Of Events			
	01	Event MOTOR VEH IN TRANSPORT		
	02	Event PARKED MOTOR VEHICLE		
	03	Event		
04	Event			
UNIT INDIVIDUAL	Individual			
	Driver EDEN MARIE HARDING		Citations Issued 2	Sex FEMALE
	Address 220 PILGRIM DR WISCONSIN DELLS, WI 53965 , US		Date of Birth 11/05/1991	Race
Driver License Number H6352139190500		STATE: WISCONSIN COUNTRY: UNITED STATES		
UNIT 02	Safety Equipment		On Duty Crash	
	Row 01 - FRONT ROW		Seat Position 07 - LEFT	
	Helmet Use		Safety Equipment SHOULDER & LAP BELT	
	Eye Protection		Helmet Compliance	
	Tint Compliance		Airbag NON DEPLOYED	
	Injury		Injury Severity SUSPECTED MINOR INJURY	
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED
Medical Transport EMS GROUND		EMS Agency Identifier 6001024		EMS Run #
Hospital REEDSBURG AREA MED CTR		Date of Death		Time of Death
Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)		
Distracted By Action NOT DISTRACTED				
Non Motorist		Striking Unit #		Location
Prior Action				

UNIT	INDIVIDUAL				
	Action				
	Action Other			To/From School	
	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type	Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results	
	Drug Type				
	Individual Condition APPEARED NORMAL				
	Violations				
	02	01	UTC Number AL8555794	Issue To? 001	Statute Number 346.13(1)
02	01	UTC Number AL8555783	Issue To? 001	Statute Number 346.57(2)	Description UNREASONABLE AND IMPRUDENT SPEED