

9PL010TWTG
R21-12123

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

9PL010TWTG

Document Number Override		Primary Crash Document #		Agency Crash Number		Investigating Officer/Deputy A. REITHMEYER	
Crash Date 11/10/2021		Crash Time 07:00 PM		Date Arrived 11/10/2021		Time Arrived 07:04 PM	
Date Notified 11/10/2021		Time Notified 07:00 PM		Total Units 02		Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure		<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended		<input type="checkbox"/> Secondary Crash	

Description

<p>Diagram</p>	Reconstruction By
	Photos By A. REITHMEYER
	Additional Information PHOTOS

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS HEADING WESTBOUND ON SILVER DR. WHEN THE VEHICLE CRASHED INTO THE REAR OF UNIT 2, WHICH WAS LEGALLY PARKED. THE OPERATOR OF UNIT 1 STATED THEY WERE LOOKING BACKWARDS THROUGH THE REAR WINDOW OF THE VEHICLE AFTER DROPPING OFF THEIR FRIEND. THERE WAS NO INJURY TO THE OPERATOR OF UNIT 1. THERE WAS NO LANE BLOCKAGE DUE TO THE ACCIDENT. THE OPERATOR OF UNIT 1 WAS ISSUED A CITATION FOR INATTENTIVE DRIVING.

Location

ON 112 SILVER DR 330 FT N OF MAPLE ST (HOUSE/BUILDING 112) IN THE CITY OF REEDSBURG IN SAUK COUNTY	Latitude 43.530741849	Longitude -89.989580055
	X Coordinate 258426.296875	Y Coordinate 4824098.5
	Structure Type HOUSE/BUILDING	

Crash Scene

First Harmful Event MOTOR VEH IN TRANSPORT	First Harmful Event Location ON ROADWAY	
Manner of Collision 03 - FRONT TO REAR	Light Condition DARK/LIGHTED	
Road Surface Condition(s) WET	Roadway Factor(s) NONE	
Environment Factor(s) NONE		
Weather Condition(s) RAIN		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE		
	Vehicle Type PASSENGER CAR	Operating As Endorsements				
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 1	Total Trailers 0	Total HazMat Types 0	
	Insurance? YES	Direction Of Travel WESTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 25	Total Lanes 2	
	Most Harmful Event: Collision With PARKED MOTOR VEHICLE		Special Function NO SPECIAL FUNCTION	Emergency Motor Vehicle Use NOT APPLICABLE		
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL	Traffic Control Inoperative/Missing NO		
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature CURVE LEFT	Road Grade LEVEL		
	Truck Bus or HazMat NO					

Vehicle

VEHICLE	License Plate Number 483DJX	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
	Vehicle Identification Number 2G4WC532651300371	Make BUICK	Year 2005	Model LACROSSE	
	Color SIL - SILVER (ALUMINUM)	Body Style 4D - 4DR		Bus Use	
	Initial Contact Point 12 - FRONT	Vehicle Damage 01 - RIGHT FRONT CORNER, 02 - RIGHT SIDE FRONT, 10 - LEFT SIDE FRONT, 11 - LEFT FRONT CORNER, 12 - FRONT			
	Extent Of Damage FUNCTIONAL DAMAGE				



UNIT	Towed Due To Damage NOT TOWED		Vehicle Removed By OPERATOR		
	What Driver Was Doing NEGOTIATING CURVE		Vehicle Factors		
	Driver Prior Action Other		NOT APPLICABLE		
	Driver Actions OPERATED MOTOR VEHICLE IN INATTENTIVE, CARELESS OR ERRATIC MANNER				
01	01	Owner Name LYLE DARWIN LINDHOLM		Owner Address 521 N GROVE ST REEDSBURG, WI 53959 , US	
		Sequence Of Events			
UNIT	01	Event MOTOR VEH IN TRANSPORT			
		Event PARKED MOTOR VEHICLE			
		Event			
		Event			
UNIT	01	Policy Holder			
		Insurance Company STATE-FARM-GENERAL-INS-CO	Individual LYLE LINDHOLM		
UNIT	01	Individual			
		Driver JOSEPH DANIEL LINDHOLM	Citations Issued 1	Sex MALE	
			Date of Birth 10/27/2003	Race WHITE	
		Address 521 N GROVE ST REEDSBURG, WI 53959 , US		Driver License Number L5344840338702 STATE: WISCONSIN COUNTRY: UNITED STATES	
01	001	Safety Equipment		On Duty Crash	
				Safety Equipment	
		Row 01 - FRONT ROW	Seat Position 07 - LEFT	SHOULDER & LAP BELT	
		Helmet Use		Helmet Compliance	
		Eye Protection		Tint Compliance	
		Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED	
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #	
Hospital		Date of Death		Time of Death	
Distracted By		Distracted By Source EXTERNAL (TO VEHICLE/NON-MOTORIST AREA)			
Distracted By Action OTHER ACTION (LOOKING AWAY FROM TASK ETC)					


UNIT	INDIVIDUAL	Non Motorist		Striking Unit #	Location	
		Prior Action				
		Action				
	Action Other					To/From School
	Drug & Alcohol		Suspected Alcohol Use NO		Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type		Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	
	Drug Type					
	Individual Condition APPEARED NORMAL					
	01	001	Violations			
UTC Number BD875499			Issue To? 001	Statute Number 346.89(1)	Description INATTENTIVE DRIVING	

Unit Summary

UNIT	02	Unit Status LEGALLY PARKED		Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE			
		Vehicle Type PASSENGER CAR					Operating As Endorsements		
		Total Occs 0		Train/Bus # Recorded		Total # Citations Issued 0		Total Trailers 0	Total HazMat Types 0
		Insurance? YES		Direction Of Travel WESTBOUND		<input type="checkbox"/> Pre CrashTire Mark		Speed Limit 25	Total Lanes 2
		Most Harmful Event: Collision With PARKED MOTOR VEHICLE			Special Function NO SPECIAL FUNCTION			Emergency Motor Vehicle Use NOT APPLICABLE	
		Traffic Way TWO-WAY, NOT DIVIDED			Traffic Control NO CONTROL			Traffic Control Inoperative/Missing NO	
		Surface Type BLACKTOP (BITUMINOUS)			Road Curvature CURVE LEFT			Road Grade LEVEL	
		Truck Bus or HazMat NO							

Vehicle

02	02	License Plate Number ACA6177		Plate Type AUT - AUTOMOBILE		St WI	Country of Issuance UNITED STATES		
		Vehicle Identification Number 1N4BL4BV1KC115178		Make NISSAN		Year 2019	Model ALTIMA		
		Color BLK - BLACK		Body Style SD - SEDAN				Bus Use	
		Initial Contact Point 06 - REAR							



9PL010TWTG
R21-12123

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

UNIT	VEHICLE	Vehicle Damage	
		Extent Of Damage FUNCTIONAL DAMAGE	06 - REAR, 07 - LEFT REAR CORNER, 08 - LEFT SIDE REAR
		Towed Due To Damage NOT TOWED	Vehicle Removed By OPERATOR
		What Driver Was Doing LEGALLY PARKED	Vehicle Factors
UNIT	VEHICLE	Driver Prior Action Other	NOT APPLICABLE
		Driver Actions NO CONTRIBUTING ACTION	
		Owner Name HOME HEALTH UNITED INC	Owner Address 2802 WALTON COMMONS LANE MADISON, WI 53718 , US
		Sequence Of Events	
02	02	01 Event PARKED MOTOR VEHICLE	
		02 Event	
		03 Event	
		04 Event	
UNIT	02	Policy Holder	
		Insurance Company SENTRY-INS-CO	Organization/Company HOME HEALTH UNITED INC