

9PL009V8WC

Document Number Override		Primary Crash Document #		Agency Crash Number		Investigating Officer/Deputy K. YEAGER	
Crash Date 12/01/2021		Crash Time 07:48 PM		Date Arrived 12/01/2021		Time Arrived 07:58 PM	
Date Notified 12/01/2021		Time Notified 07:51 PM		Total Units 02		Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input checked="" type="checkbox"/> Lane Closure		<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended		<input type="checkbox"/> Secondary Crash	

Description

<p>Diagram</p> <p>Reconstruction By</p> <p>Photos By K. YEAGER</p> <p>Additional Information NONE, PHOTOS</p>

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

ON 12/01/2021 AT APPROXIMATELY 1955 HOURS I WAS DISPATCHED TO A TWO VEHICLE CRASH WITH NO INJURIES, WITH ROAD BLOCKAGE. I RESPONDED TO THE CRASH SCENE AND OBSERVED A PICK UP TRUCK (HF2914) PARTIALLY IN THE LANE OF TRAFFIC ON VIKING DRIVE, AND PARTIALLY BLOCKING THE TRAVEL LANE ON 19TH STREET. I OBSERVED AN SUV WITH WI REGISTRATION (887TWF) FACING EASTBOUND ON 19TH STREET. I MADE CONTACT WITH BOTH DRIVERS AND THE PASSENGER AND ASKED THEM IF THEY HAD ANY INJURIES. ALL INVOLVED STATED THEY HAD NO INJURIES. I THEN SPOKE WITH UNIT TWO AND ASKED WHAT HAD HAPPENED. UNIT TWO STATED SHE WAS STOPPED AT THE STOP SIGN ON 19TH STREET WAITING TO TURN ONTO VIKING DRIVE. UNIT TWO STATED THAT UNIT ONE WAS TRAVELING NORTHBOUND ON VIKING DRIVE, AND BEGAN TO MAKE THE LEFT TURN ONTO 19TH STREET. UNIT TWO STATED SHE SAW THAT UNIT ONE WAS TAKING THE TURN TO SHARP, AND WAS GOING TO STRIKE HER, BUT SHE STATED SHE HAD A VEHICLE DIRECTLY BEHIND HER THAT WAS ALSO WAITING AT THE STOP SIGN, SO SHE COULD NOT DO ANYTHING TO AVOID THE COLLISION. UNIT TWO STATED THAT UNIT ONE DID END UP TURNING TO SHARPLY, ENTERING HER LANE AND STRUCK THE FRONT DRIVER SIDE CORNER OF HER VEHICLE. AFTER SPEAKING WITH UNIT TWO, I THEN WENT TO SPEAK WITH UNIT ONE. UNIT ONE STATED THAT SHE WAS JUST COMING BACK FROM THE BP GAS STATION, AND WENT TO TURN ONTO 19TH STREET, WHEN HER PASSENGER MADE A COMMENT TO HER TO WATCH OUT, AND THAT SHE WAS TURNING TO SHARP. UNIT ONE STATED THAT SHE THEN FELT THE IMPACT. UNIT ONE STATED SHE ALWAYS HAS TROUBLE WITH THIS INTERSECTION, AND STATED THAT SHE ALSO DOES NOT USUALLY

9PL009V8WC
R21-12892

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

DRIVE AT NIGHT. I ASKED UNIT ONE IF SHE SAW UNIT TWO WAITING AT THE STOP SIGN, AND SHE STATED SHE DID, BUT MENTIONED THAT SHE HAS CATARACTS AND STATED SHE JUST SEEN A BLUR FROM THE VEHICLES HEAD LIGHTS. I THEN SPOKE WITH UNIT ONE ABOUT INSURANCE FOR THE VEHICLE AND SHE STATED SHE IS NOT THE OWNER, BUT SHE BELIEVES THE OWNER HAS INSURANCE. FOLLOW UP WITH THE REGISTERED OWNER CONTINUES.

Location

ON 19TH ST 26 FT W OF VIKING DR/ CTHH WB IN THE CITY OF REEDSBURG IN SAUK COUNTY	Latitude 43.547032872	Longitude -89.984634834
	X Coordinate 258890.890625	Y Coordinate 4825893.5
	Structure Type	

Crash Scene

First Harmful Event MOTOR VEH IN TRANSPORT		First Harmful Event Location ON ROADWAY	
Manner of Collision 02 - FRONT TO FRONT		Light Condition DARK/LIGHTED	
Road Surface Condition(s) DRY		Roadway Factor(s) NONE	
Environment Factor(s) NONE			
Weather Condition(s) CLEAR			
Animal Type		Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY		Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land		Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location INTERSECTION	Intersection Type T-INTERSECTION	
Closure Type FULL CLOSURE		Reasons for Closure LAW ENFORCEMENT	
Date Initial Lane/Rd Closed 12/01/2021	Time Initial Lane/Rd Closed 07:58 PM		
Date All Lanes Open 12/01/2021	Time All Lanes Open 08:20 PM	Date Scene Cleared 12/01/2021	Time Scene Cleared 08:35 PM

Unit Summary

UNIT 01	Unit Status IN TRANSIT		Vehicle Operating As Classification D CLASS		Unit Type TRUCK	
	Vehicle Type UTILITY TRUCK/PICKUP TRUCK				Operating As Endorsements	
	Total Occs 2	Train/Bus # Recorded	Total # Citations Issued 2	Total Trailers 0	Total HazMat Types 0	
	Insurance? NO	Direction Of Travel WESTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 25	Total Lanes 2	
	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type CONCRETE		Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO					
	Vehicle					
	License Plate Number HF2914		Plate Type LTK - LIGHT TRUCK	St WI	Country of Issuance UNITED STATES	

9PL009V8WC
R21-12892

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

01 UNIT VEHICLE	01	Vehicle Identification Number 3B7HC13Z4VG713593	Make DODGE	Year 1997	Model RAM 1500	
		Color BRO - BROWN	Body Style PK - PICKUP	Bus Use		
		Initial Contact Point 11 - LEFT FRONT CORNER	Vehicle Damage 11 - LEFT FRONT CORNER			
		Extent Of Damage MINOR DAMAGE				
		Towed Due To Damage NOT TOWED	Vehicle Removed By OPERATOR			
		What Driver Was Doing LEFT TURN	Vehicle Factors			
		Driver Prior Action Other	NOT APPLICABLE			
01 UNIT VEHICLE		Driver Actions IMPROPER TURN, FAILED TO KEEP IN DESIGNATED LANE				
	01	Owner Name GLEN W LIND (608) 415-3197	Owner Address 401 N WALNUT ST APT G08 REEDSBURG, WI 53959 , US			
Sequence Of Events						
	01	Event MOTOR VEH IN TRANSPORT				
	02	Event MOTOR VEH IN TRANSPORT				
	03	Event				
	04	Event				
Individual						
01 UNIT INDIVIDUAL		Driver DANNA LOUISE GROOM (608) 415-3197	Citations Issued 2	Sex FEMALE		
			Date of Birth 01/22/1958	Race WHITE		
		Address 401 N WALNUT ST APT G08 REEDSBURG, WI 53959 , US	Driver License Number G6501725852202 STATE: WISCONSIN COUNTRY: UNITED STATES			
Safety Equipment						
		On Duty Crash	Safety Equipment			
	01	Row 01 - FRONT ROW	Seat Position 07 - LEFT	SHOULDER & LAP BELT		
		Helmet Use		Helmet Compliance		
		Eye Protection		Tint Compliance		
01 UNIT INDIVIDUAL	001	Injury	Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED		
		Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED	
		Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #	

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	Hospital		Date of Death		Time of Death	
	Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)			
	Distracted By Action NOT DISTRACTED					
	Non Motorist		Striking Unit #		Location	
	Prior Action					
	Action					
	Action Other					To/From School
	Drug & Alcohol		Suspected Alcohol Use NO		Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type		Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	
Drug Type						
Individual Condition APPEARED NORMAL						
UNIT	Individual					
	Passenger SANDRA R. DUBLIN (608) 415-3485		Citations Issued 0		Sex FEMALE	
	Address 1250 19TH ST #10 REEDSBURG, WI 53959 , US		Date of Birth 11/24/1965		Race WHITE	
	Driver License Number D1457966592407 STATE: WISCONSIN COUNTRY: UNITED STATES					
	Safety Equipment		On Duty Crash		Safety Equipment	
	Row 01 - FRONT ROW		Seat Position 09 - RIGHT		SHOULDER & LAP BELT	
	Helmet Use		Helmet Compliance			
	Eye Protection		Tint Compliance			
	Injury		Injury Severity NO APPARENT INJURY		Airbag NON DEPLOYED	
	Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED	
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #		
Hospital		Date of Death		Time of Death		

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	Distracted By	Distracted By Source		
		Distracted By Action		
	Non Motorist	Striking Unit #	Location	
		Prior Action		
	INDIVIDUAL	Action		
		Action Other		To/From School
		Drug & Alcohol	Suspected Alcohol Use NO	Suspected Drug Use NO
		Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results
		Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results
		Drug Type		
	Individual Condition APPEARED NORMAL			
	Violations			
01	UTC Number BD875174	Issue To? 001	Statute Number 346.13(1)	Description UNSAFE LANE DEVIATION
02	UTC Number AL852744	Issue To? 001	Statute Number 344.62(1)	Description OPERATE MOTOR VEHICLE W/O INSURANCE

Unit Summary

UNIT	02	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS	Unit Type AUTOMOBILE	
		Vehicle Type (SPORT) UTILITY VEHICLE	Operating As Endorsements		
		Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0
		Insurance? YES	Direction Of Travel EASTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 25
		Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT	Special Function NO SPECIAL FUNCTION	Emergency Motor Vehicle Use NOT APPLICABLE	
		Traffic Way TWO-WAY, NOT DIVIDED	Traffic Control STOP SIGN	Traffic Control Inoperative/Missing NO	
		Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT	Road Grade LEVEL	
		Truck Bus or HazMat NO			
		Vehicle			
		License Plate Number 887TWF	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES

9PL009V8WC
R21-12892

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

02	UNIT	VEHICLE	Vehicle Identification Number 3GKALMEXXJL128943	Make GENERAL MOTORS COR	Year 2018	Model TERRAIN		
			Color GRY - GRAY	Body Style UT - SPORT UTILITY VEHICLE	Bus Use			
			Initial Contact Point 11 - LEFT FRONT CORNER	Vehicle Damage 11 - LEFT FRONT CORNER				
			Extent Of Damage FUNCTIONAL DAMAGE					
			Towed Due To Damage NOT TOWED	Vehicle Removed By OPERATOR				
			What Driver Was Doing OTHER	Vehicle Factors NOT APPLICABLE				
			Driver Prior Action Other STOPPED AT STOP SIGN, WAITING TO TURN.					
02	UNIT	VEHICLE	Driver Actions NO CONTRIBUTING ACTION					
			Owner Name SHANNON RENEE SCHULZ (608) 495-2188	Owner Address 1661 19TH ST # 114 REEDSBURG, WI 53959 , US				
Sequence Of Events								
01	UNIT	VEHICLE	Event MOTOR VEH IN TRANSPORT					
			Event MOTOR VEH IN TRANSPORT					
			Event					
			Event					
Policy Holder								
02	UNIT	Insurance Company WEST-BEND-MUTUAL-INS-CO		Individual SHANNON SCHULZ				
		Individual						
02	UNIT	INDIVIDUAL	Driver SHANNON RENEE SCHULZ (608) 495-2188	Citations Issued 0	Sex FEMALE			
			Date of Birth 02/06/1993		Race WHITE			
			Address 1661 19TH ST # 114 REEDSBURG, WI 53959 , US		Driver License Number S4207969354607 STATE: WISCONSIN COUNTRY: UNITED STATES			
Safety Equipment								
02	UNIT	INDIVIDUAL	On Duty Crash		Safety Equipment SHOULDER & LAP BELT			
			Row 01 - FRONT ROW	Seat Position 07 - LEFT				
			Helmet Use		Helmet Compliance			
			Eye Protection		Tint Compliance			
02	UNIT	INDIVIDUAL	Injury NO APPARENT INJURY		Airbag NON DEPLOYED			
			Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE	Trapped/Extricated NOT TRAPPED			

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT INDIVIDUAL 02 003	Medical Transport NOT TRANSPORTED	EMS Agency Identifier	EMS Run #
	Hospital	Date of Death	Time of Death
	Distracted By	Distracted By Source NOT APPLICABLE (NOT DISTRACTED)	
	Distracted By Action NOT DISTRACTED		
	Non Motorist	Striking Unit #	Location
	Prior Action		
	Action		
	Action Other		To/From School
	Drug & Alcohol	Suspected Alcohol Use NO	Suspected Drug Use NO
	Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type	Alcohol Test Results
	Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results
	Drug Type		
	Individual Condition APPEARED NORMAL		