

9PL010TWTJ  
R21-13111

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

9PL010TWTJ

Document Number Override		Primary Crash Document #		Agency Crash Number		Investigating Officer/Deputy <b>J. WILLIAMS</b>	
Crash Date <b>12/07/2021</b>		Crash Time <b>05:25 PM</b>		Date Arrived <b>12/07/2021</b>		Time Arrived <b>05:31 PM</b>	
Date Notified <b>12/07/2021</b>		Time Notified <b>05:29 PM</b>		Total Units <b>02</b>		Total Injured <b>00</b>	Total Killed <b>00</b>
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold	
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related <b>NO</b>		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type <b>DT4000 (STANDARD CRASH)</b>				<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

Diagram <p style="text-align: center;">Not to Scale</p> <p style="text-align: center;">N Wellington Ave</p> <p style="text-align: center;">N. Dewey Ave</p>	Reconstruction By
	Photos By <b>J.WILLIAMS</b>
	Additional Information <b>NONE, PHOTOS</b>

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS OPERATING SOUTHBOUND ON N. DEWEY AVE NEAR WELLINGTON DR. WHILE UNIT 1 WAS PASSING BY THE INTERSECTION OF WELLINGTON DR, UNIT 2 TURNED OUT ONTO N. DEWEY AVE FROM WELLINGTON AVE TO MAKE A LEFT TURN (SOUTHBOUND) AND RAN INTO THE REAR DRIVER'S SIDE CORNER OF UNIT 1. UNIT 2 ADVISED HE DID NOT SEE UNIT 1 AND CLAIMED IT WAS IN HIS BLIND SPOT. UNIT 2 WAS ISSUED AND EXPLAINED A CITATION FOR FAILING TO YIELD RIGHT OF WAY FROM A STOP SIGN.

9PL010TWTJ  
R21-13111

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

Location

ON WELLINGTON DR 9 FT E OF N DEWEY AVE IN THE CITY OF REEDSBURG IN SAUK COUNTY	Latitude <b>43.53608709</b>	Longitude <b>-89.994550009</b>
	X Coordinate <b>258046.0625</b>	Y Coordinate <b>4824706.5</b>
	Structure Type <b>NO STRUCTURE</b>	

Crash Scene

First Harmful Event <b>MOTOR VEH IN TRANSPORT</b>	First Harmful Event Location <b>ON ROADWAY</b>	
Manner of Collision <b>05 - REAR TO SIDE</b>	Light Condition <b>DARK/LIGHTED</b>	
Road Surface Condition(s) <b>DRY</b>	Roadway Factor(s)  <b>NONE</b>	
Environment Factor(s) <b>NONE</b>		
Weather Condition(s) <b>CLEAR</b>		
Animal Type	Relation To Trafficway <b>TRAFFICWAY - ON ROAD</b>	
Crash Classification - Location <b>PUBLIC PROPERTY</b>	Crash Classification - Jurisdiction <b>NO SPECIAL JURISDICTION</b>	
Tribal Land	Access Control <b>NO CONTROL</b>	Special Study
Within Interchange Area <b>NO</b>	Junction Location <b>INTERSECTION</b>	Intersection Type <b>T-INTERSECTION</b>

Unit Summary

<b>UNIT</b>	Unit Status <b>IN TRANSIT</b>	Vehicle Operating As Classification <b>D CLASS</b>		Unit Type <b>AUTOMOBILE</b>	
	Vehicle Type <b>PASSENGER CAR</b>	Operating As Endorsements			
	Total Occs <b>1</b>	Train/Bus # Recorded	Total # Citations Issued <b>0</b>	Total Trailers <b>0</b>	Total HazMat Types <b>0</b>
	Insurance? <b>YES</b>	Direction Of Travel <b>SOUTHBOUND</b>	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit <b>25</b>	Total Lanes <b>2</b>
	Most Harmful Event: Collision With <b>MOTOR VEH IN TRANSPORT</b>	Special Function <b>NO SPECIAL FUNCTION</b>		Emergency Motor Vehicle Use <b>NOT APPLICABLE</b>	
	Traffic Way <b>TWO-WAY, NOT DIVIDED</b>	Traffic Control <b>NO CONTROL</b>		Traffic Control Inoperative/Missing <b>NO</b>	
	Surface Type <b>BLACKTOP (BITUMINOUS)</b>	Road Curvature <b>STRAIGHT</b>		Road Grade <b>LEVEL</b>	
	Truck Bus or HazMat <b>NO</b>				

Vehicle

<b>UNIT</b>	<b>VEHICLE</b>	License Plate Number <b>161YFY</b>	Plate Type <b>AUT - AUTOMOBILE</b>	St <b>WI</b>	Country of Issuance <b>UNITED STATES</b>	
		Vehicle Identification Number <b>2FMDK4JC3EBA63154</b>	Make <b>FORD</b>	Year <b>2014</b>	Model <b>EDGE</b>	
		Color <b>ONG - ORANGE</b>	Body Style <b>UT - SPORT UTILITY VEHICLE</b>		Bus Use	
		Initial Contact Point <b>08 - LEFT SIDE REAR</b>	Vehicle Damage			
		Extent Of Damage <b>MINOR DAMAGE</b>	<b>08 - LEFT SIDE REAR</b>			



9PL010TWTJ  
R21-13111

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

UNIT	Towed Due To Damage <b>NOT TOWED</b>		Vehicle Removed By <b>OPERATOR</b>		
	What Driver Was Doing <b>GOING STRAIGHT</b>		Vehicle Factors		
	Driver Prior Action Other		<b>NOT APPLICABLE</b>		
	Driver Actions <b>NO CONTRIBUTING ACTION</b>				
01	01	Owner Name <b>JODY LYNNE SIMON (608) 434-5016</b>		Owner Address <b>2011 N DEWEY AVE REEDSBURG, WI 53959 , US</b>	
		<b>Sequence Of Events</b>			
UNIT	01	Event <b>MOTOR VEH IN TRANSPORT</b>			
		Event <b>MOTOR VEH IN TRANSPORT</b>			
		Event			
		Event			
UNIT	01	<b>Policy Holder</b>			
		Insurance Company <b>ERIE-INS-CO</b>	Individual <b>JODY SIMON</b>		
UNIT	01	<b>Individual</b>			
		Driver <b>JODY LYNNE SIMON (608) 434-5016</b>	Citations Issued <b>0</b>	Sex <b>FEMALE</b>	
		Date of Birth <b>08/23/1960</b>		Race	
		Address <b>2011 N DEWEY AVE REEDSBURG, WI 53959 , US</b>		Driver License Number <b>S5504326080308 STATE: WISCONSIN COUNTRY: UNITED STATES</b>	
01	001	<b>Safety Equipment</b>		On Duty Crash	
				Safety Equipment	
		Row <b>01 - FRONT ROW</b>	Seat Position <b>07 - LEFT</b>	<b>SHOULDER &amp; LAP BELT</b>	
		Helmet Use		Helmet Compliance	
		Eye Protection		Tint Compliance	
		<b>Injury</b>		Injury Severity <b>NO APPARENT INJURY</b>	Airbag <b>NON DEPLOYED</b>
Ejected <b>NOT EJECTED</b>		Ejection Path <b>NOT EJECTED/NOT APPLICABLE</b>		Trapped/Extricated <b>NOT TRAPPED</b>	
Medical Transport <b>NOT TRANSPORTED</b>		EMS Agency Identifier		EMS Run #	
Hospital		Date of Death		Time of Death	
<b>Distracted By</b>		Distracted By Source <b>NOT APPLICABLE (NOT DISTRACTED)</b>			
<b>Distracted By Action</b>		<b>NOT DISTRACTED</b>			


WISCONSIN MOTOR VEHICLE  
CRASH REPORT

<b>UNIT</b>	<b>INDIVIDUAL</b>	<b>Non Motorist</b>		Striking Unit #	Location		
		Prior Action					
		Action					
	Action Other					To/From School	
	<b>01</b>	<b>001</b>	<b>Drug &amp; Alcohol</b>		Suspected Alcohol Use <b>NO</b>	Suspected Drug Use <b>NO</b>	
			Alcohol Test Given <b>TEST NOT GIVEN</b>		Alcohol Test Type	Alcohol Test Results	
			Drug Test Given <b>TEST NOT GIVEN</b>		Drug Test Type	Drug Test Results	
			Drug Type				
			Individual Condition <b>APPEARED NORMAL</b>				

**Unit Summary**

<b>UNIT</b>	<b>02</b>	Unit Status <b>IN TRANSIT</b>		Vehicle Operating As Classification <b>D CLASS</b>		Unit Type <b>AUTOMOBILE</b>		
		Vehicle Type <b>PASSENGER CAR</b>					Operating As Endorsements	
		Total Occs <b>1</b>	Train/Bus # Recorded	Total # Citations Issued <b>1</b>	Total Trailers <b>0</b>	Total HazMat Types <b>0</b>		
		Insurance? <b>YES</b>	Direction Of Travel <b>WESTBOUND</b>	<input type="checkbox"/> Pre Crash <input type="checkbox"/> Tire Mark	Speed Limit <b>25</b>	Total Lanes <b>2</b>		
		Most Harmful Event: Collision With <b>MOTOR VEH IN TRANSPORT</b>			Special Function <b>NO SPECIAL FUNCTION</b>		Emergency Motor Vehicle Use <b>NOT APPLICABLE</b>	
		Traffic Way <b>TWO-WAY, NOT DIVIDED</b>		Traffic Control <b>STOP SIGN</b>		Traffic Control Inoperative/Missing <b>NO</b>		
		Surface Type <b>BLACKTOP (BITUMINOUS)</b>		Road Curvature <b>STRAIGHT</b>		Road Grade <b>LEVEL</b>		
		Truck Bus or HazMat <b>NO</b>						

<b>UNIT</b>	<b>VEHICLE</b>	<b>Vehicle</b>				
		License Plate Number <b>289PJS</b>	Plate Type <b>AUT - AUTOMOBILE</b>	St <b>WI</b>	Country of Issuance <b>UNITED STATES</b>	
		Vehicle Identification Number <b>4T1BB46K59U107226</b>	Make <b>TOYOTA</b>	Year <b>2009</b>	Model <b>CAMRY HYBR</b>	
		Color <b>BLU - BLUE</b>	Body Style <b>4D - 4DR</b>		Bus Use	
		Initial Contact Point <b>01 - RIGHT FRONT CORNER</b>	Vehicle Damage			
		Extent Of Damage <b>FUNCTIONAL DAMAGE</b>	<b>01 - RIGHT FRONT CORNER</b>			
		Towed Due To Damage <b>NOT TOWED</b>	Vehicle Removed By <b>OPERATOR</b>			



WISCONSIN MOTOR VEHICLE  
CRASH REPORT

UNIT VEHICLE	What Driver Was Doing <b>LEFT TURN</b>		Vehicle Factors	
	Driver Prior Action Other		<b>NOT APPLICABLE</b>	
	Driver Actions <b>FAILED TO YIELD RIGHT-OF-WAY</b>			
	Owner Name <b>MICHAEL DONALD GOODMAN (608) 495-0207</b>		Owner Address <b>1580 CANTERBURY DR REEDSBURG, WI 53959 , US</b>	
UNIT 02	<b>Sequence Of Events</b>			
	01	Event <b>MOTOR VEH IN TRANSPORT</b>		
	02	Event <b>LEFT TURN</b>		
	03	Event <b>MOTOR VEH IN TRANSPORT</b>		
	04	Event		
UNIT	<b>Policy Holder</b>			
	Insurance Company <b>WEST-BEND-MUTUAL-INS-CO</b>		Individual <b>MICHAEL GOODMAN</b>	
UNIT INDIVIDUAL	<b>Individual</b>			
	Driver <b>MICHAEL DONALD GOODMAN (608) 495-0207</b>		Citations Issued <b>1</b>	Sex <b>MALE</b>
	Address <b>1580 CANTERBURY DR REEDSBURG, WI 53959 , US</b>		Date of Birth <b>10/18/1955</b>	Race <b>WHITE</b>
			Driver License Number <b>G3555445537801 STATE: WISCONSIN COUNTRY: UNITED STATES</b>	
UNIT 02	<b>Safety Equipment</b>		On Duty Crash	
			Safety Equipment	
	Row <b>01 - FRONT ROW</b>	Seat Position <b>07 - LEFT</b>	<b>SHOULDER &amp; LAP BELT</b>	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	<b>Injury</b>		Injury Severity <b>NO APPARENT INJURY</b>	Airbag <b>NON DEPLOYED</b>
	Ejected <b>NOT EJECTED</b>	Ejection Path <b>NOT EJECTED/NOT APPLICABLE</b>		Trapped/Extricated <b>NOT TRAPPED</b>
	Medical Transport <b>NOT TRANSPORTED</b>		EMS Agency Identifier	EMS Run #
	Hospital		Date of Death	Time of Death
	<b>Distracted By</b>		Distracted By Source <b>UNKNOWN</b>	
Distracted By Action <b>UNKNOWN</b>				
<b>Non Motorist</b>		Striking Unit #	Location	

UNIT	Prior Action							
	Action							
	Action Other			To/From School				
	<b>Drug &amp; Alcohol</b>		Suspected Alcohol Use <b>NO</b>	Suspected Drug Use <b>NO</b>				
	Alcohol Test Given <b>TEST NOT GIVEN</b>		Alcohol Test Type	Alcohol Test Results				
	Drug Test Given <b>TEST NOT GIVEN</b>		Drug Test Type	Drug Test Results				
	Drug Type							
	Individual Condition <b>APPEARED NORMAL</b>							
	<b>Violations</b>							
	02	002	01	<table border="1"> <tr> <td>UTC Number <b>BD875529</b></td> <td>Issue To? <b>002</b></td> <td>Statute Number <b>346.18(3)</b></td> <td>Description <b>FAIL/YIELD RIGHT/WAY FROM STOP SIGN</b></td> </tr> </table>		UTC Number <b>BD875529</b>	Issue To? <b>002</b>	Statute Number <b>346.18(3)</b>
UTC Number <b>BD875529</b>	Issue To? <b>002</b>	Statute Number <b>346.18(3)</b>	Description <b>FAIL/YIELD RIGHT/WAY FROM STOP SIGN</b>					