

WISCONSIN MOTOR VEHICLE
CRASH REPORT

9PL010TWTP

Document Number Override		Primary Crash Document #		Agency Crash Number		Investigating Officer/Deputy J. WILLIAMS	
Crash Date 12/27/2021		Crash Time 10:55 AM		Date Arrived 12/27/2021		Time Arrived 10:59 AM	
Date Notified 12/27/2021		Time Notified 10:57 AM		Total Units 03		Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure		<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)				<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

Diagram		Reconstruction By	
<p style="text-align: center;">Not to Scale</p> <p style="text-align: center;">N. Dewey Ave</p>		Photos By J. WILLIAMS	
		Additional Information NONE, PHOTOS	

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS OPERATING NORTHBOUND IN THE 1600 BLOCK OF N. DEWEY AVE. UNIT 2 AND 3 WERE LEGALLY PARKED ON THE RIGHT HAND SIDE OF THE ROAD UNATTENDED IN THE 1600 BLOCK OF N. DEWEY AVE ALSO FACING NORTHBOUND. UNIT 1 ADVISED HE LOOKED AWAY FROM THE ROADWAY TO CHECK HIS GPS WHEN HE SIDE SWIPE THE DRIVER'S SIDE OF BOTH UNIT'S 2 AND 3. UNIT 1 WAS ISSUED A CITATION FOR INATTENTIVE DRIVING. UNIT 1'S VEHICLE WAS REMOVED BY REEDSBURG SALVAGE. INSURANCE INFORMATION EXCHANGED BETWEEN ALL PARTIES.

Location

ON N DEWEY AVE 295 FT S OF 19TH ST IN THE CITY OF REEDSBURG IN SAUK COUNTY	Latitude 43.547560215	Longitude -89.994584554
	X Coordinate 258089.203125	Y Coordinate 4825981
	Structure Type NO STRUCTURE	

Crash Scene

First Harmful Event PARKED MOTOR VEHICLE	First Harmful Event Location ON ROADWAY	
Manner of Collision 07 - SIDESWIPE/SAME DIRECTION	Light Condition DAYLIGHT	
Road Surface Condition(s) WET, SLUSH	Roadway Factor(s) NONE	
Environment Factor(s) NONE		
Weather Condition(s) CLOUDY		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 1	Total Trailers 0	Total HazMat Types 0
	Insurance? YES	Direction Of Travel NORTHBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 25	Total Lanes 2
	Most Harmful Event: Collision With PARKED MOTOR VEHICLE	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO				

Vehicle

UNIT	VEHICLE	License Plate Number 192ZWE	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
		Vehicle Identification Number 1N4AL3AP8GC171909	Make NISSAN	Year 2016	Model ALTIMA	
		Color SIL - SILVER (ALUMINUM)	Body Style SD - SEDAN		Bus Use	
		Initial Contact Point 02 - RIGHT SIDE FRONT	Vehicle Damage			
		Extent Of Damage DISABLING DAMAGE	02 - RIGHT SIDE FRONT			



UNIT	Towed Due To Damage TOWED DUE TO DISABLING DAMAGE		Vehicle Removed By REEDSBURG SALVAGE		
	What Driver Was Doing GOING STRAIGHT		Vehicle Factors		
	Driver Prior Action Other		NOT APPLICABLE		
	Driver Actions FAILED TO KEEP IN DESIGNATED LANE				
01	01	Owner Name ANTHONY PETER LAMBO (414) 807-0639		Owner Address 6340 STATE ROAD 144 WEST BEND, WI 53095 , US	
		Sequence Of Events			
UNIT	01	Event MOTOR VEH IN TRANSPORT			
		Event PARKED MOTOR VEHICLE			
		Event PARKED MOTOR VEHICLE			
		Event			
UNIT	01	Policy Holder			
		Insurance Company STATE-FARM-GENERAL-INS-CO	Individual ANTHONY LAMBO		
UNIT	01	Individual			
		Driver ANTHONY PETER LAMBO (414) 807-0639		Citations Issued 1	Sex MALE
		Date of Birth 09/25/1962		Race WHITE	
		Address 6340 STATE ROAD 144 WEST BEND, WI 53095 , US		Driver License Number L5100156234509 STATE: WISCONSIN COUNTRY: UNITED STATES	
01	001	Safety Equipment		On Duty Crash	
		Safety Equipment			
		Row 01 - FRONT ROW	Seat Position 07 - LEFT	SHOULDER & LAP BELT	
		Helmet Use		Helmet Compliance	
Eye Protection		Tint Compliance			
Injury		Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED		
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED	
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #	
Hospital		Date of Death		Time of Death	
Distracted By		Distracted By Source OTHER ELECTRONIC DEVICE			
Distracted By Action OTHER ACTION (LOOKING AWAY FROM TASK ETC)					


UNIT INDIVIDUAL	Non Motorist		Striking Unit #	Location	
	Prior Action				
	Action				
	Action Other			To/From School	
	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type	Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results	
	Drug Type				
	Individual Condition APPEARED NORMAL				
	Violations				
01	001	UTC Number BD875557	Issue To? 001	Statute Number 346.89(1)	Description INATTENTIVE DRIVING

Unit Summary

UNIT 02	Unit Status LEGALLY PARKED		Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR				Operating As Endorsements	
	Total Occs 0	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0	
	Insurance? YES	Direction Of Travel NORTHBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 25	Total Lanes 2	
	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO					

Vehicle

UNIT 02	License Plate Number DC23532		Plate Type AUT - AUTOMOBILE	St IL	Country of Issuance UNITED STATES
	Vehicle Identification Number 1G1PC5SB6D7100787		Make CHEVROLET	Year 2013	Model CRUZE
	Color BLU - BLUE		Body Style 4D - 4DR		Bus Use
	Initial Contact Point 08 - LEFT SIDE REAR				



UNIT VEHICLE	Vehicle Damage	
	Extent Of Damage FUNCTIONAL DAMAGE	08 - LEFT SIDE REAR, 09 - LEFT SIDE MIDDLE, 10 - LEFT SIDE FRONT
	Towed Due To Damage NOT TOWED	Vehicle Removed By OPERATOR
	What Driver Was Doing LEGALLY PARKED	Vehicle Factors NOT APPLICABLE
UNIT VEHICLE	Driver Actions NO CONTRIBUTING ACTION	
	Owner Name VICKY J TAYLOR	Owner Address 2441 HOLMES ST APT 14 ROCKFORD, IL 61108 7875, US
Sequence Of Events		
UNIT VEHICLE	01	Event PARKED MOTOR VEHICLE
	02	Event MOTOR VEH IN TRANSPORT
	03	Event
	04	Event
Policy Holder		
UNIT	Insurance Company GENERAL-CASUALTY-INS-CO	Individual VICKY TAYLOR

Unit Summary

UNIT VEHICLE	03	Unit Status LEGALLY PARKED	Vehicle Operating As Classification D CLASS	Unit Type AUTOMOBILE	
		Vehicle Type PASSENGER CAR	Operating As Endorsements		
		Total Occs 0	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0
		Insurance? YES	Direction Of Travel NORTHBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 25
		Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT		Special Function NO SPECIAL FUNCTION	Emergency Motor Vehicle Use NOT APPLICABLE
		Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL	Traffic Control Inoperative/Missing NO
		Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT	Road Grade LEVEL
		Truck Bus or HazMat NO			

Vehicle

UNIT VEHICLE	03	License Plate Number CA36213	Plate Type AUT - AUTOMOBILE	St IL	Country of Issuance UNITED STATES
		Vehicle Identification Number 1HGCP2F8XBA049111	Make HONDA	Year 2011	Model ACCORD
		Color GRY - GRAY	Body Style 4D - 4DR		Bus Use

9PL010TWTP
R21-14085

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

UNIT	VEHICLE	Initial Contact Point 09 - LEFT SIDE MIDDLE	Vehicle Damage 08 - LEFT SIDE REAR, 09 - LEFT SIDE MIDDLE, 10 - LEFT SIDE FRONT	
		Extent Of Damage FUNCTIONAL DAMAGE		
	Towed Due To Damage NOT TOWED	Vehicle Removed By OWNER		
	What Driver Was Doing LEGALLY PARKED	Vehicle Factors		
	Driver Prior Action Other	NOT APPLICABLE		
UNIT	VEHICLE	Driver Actions NO CONTRIBUTING ACTION		
		Owner Name CHRISTOPHER F MCHENRY (815) 821-9084	Owner Address 1650 N DEWEY AVE #36 REEDSBURG, WI 53959 , US	
		Sequence Of Events		
03	03	Event 01 PARKED MOTOR VEHICLE		
		Event 02 MOTOR VEH IN TRANSPORT		
		Event		
		Event		
UNIT	VEHICLE	Policy Holder		
		Insurance Company VIVA SEGUROS - ALAMO	Individual CHRISTOPHER MCHENRY	