

9PL01884HJ  
CASE#R21-1847

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

9PL01884HJ

Document Number Override		Primary Crash Document #		Agency Crash Number		Investigating Officer/Deputy <b>T. KNUTH</b>	
Crash Date <b>02/17/2021</b>		Crash Time <b>10:08 AM</b>		Date Arrived <b>02/17/2021</b>		Time Arrived <b>10:15 AM</b>	
Date Notified <b>02/17/2021</b>		Time Notified <b>10:08 AM</b>		Total Units <b>02</b>		Total Injured <b>00</b>	Total Killed <b>00</b>
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold	
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related <b>NO</b>		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type <b>DT4000 (STANDARD CRASH)</b>				<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

Diagram	Reconstruction By
	Photos By <b>T. KNUTH #130</b>
	Additional Information <b>PHOTOS</b>

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS DRIVING NORTH ON THOMAS RD AND BEGAN TO TURN THE STEERING WHEEL TO NEGOTIATE A LEFT CURVE WHEN OPERATOR LOST CONTROL OF UNIT AND SLID SIDWAYS AND STRUCK UNIT 2. UNIT 2 WAS LEGALLY PARKED ON THE EAST SIDE OF THE STREET FACING NORTH. THE FRONT PASSENGER SIDE OF UNIT 1 STRUCK THE REAR DRIVER'S SIDE OF UNIT 2. BOTH UNITS SUSTAINED MINOR/FUNCTIONAL DAMAGE. THE ROADWAY WAS SNOW AND ICE COVERED FROM APPROXIMATELY 2 WEEKS OF SNOW ACCUMULATION AND BELOW ZERO TEMPERATURES. THE ROADWAY WAS SLIPPERY DUE TO THESE CONDITIONS. OPERATOR OF UNIT 1 STATED HE WAS DRIVING LESS THAN THE SPEED LIMIT WHEN HE LOST CONTROL AND LOST CONTROL WHEN HE BEGAN TO TURN THE STEERING WHEEL. NOTHING FURTHER.

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

Location

ON THOMAS RD 431 FT S OF BARBARA ANN DR IN THE CITY OF REEDSBURG IN SAUK COUNTY	Latitude <b>43.551992131</b>	Longitude <b>-90.010539174</b>
	X Coordinate <b>256818.109375</b>	Y Coordinate <b>4826519.5</b>
	Structure Type	

Crash Scene


First Harmful Event <b>PARKED MOTOR VEHICLE</b>	First Harmful Event Location <b>ON ROADWAY</b>	
Manner of Collision <b>03 - FRONT TO REAR</b>	Light Condition <b>DAYLIGHT</b>	
Road Surface Condition(s) <b>SNOW, ICE</b>	Roadway Factor(s)  <b>ROAD SURFACE CONDITION (WET, ICY, SNOW, SLUSH, ETC)</b>	
Environment Factor(s) <b>WEATHER CONDITIONS</b>		
Weather Condition(s) <b>CLEAR</b>		
Animal Type	Relation To Trafficway <b>TRAFFICWAY - ON ROAD</b>	
Crash Classification - Location <b>PUBLIC PROPERTY</b>	Crash Classification - Jurisdiction <b>NO SPECIAL JURISDICTION</b>	
Tribal Land	Access Control <b>NO CONTROL</b>	Special Study
Within Interchange Area <b>NO</b>	Junction Location <b>NON-JUNCTION</b>	Intersection Type <b>NOT AN INTERSECTION</b>

Unit Summary

<b>UNIT</b>	Unit Status <b>IN TRANSIT</b>	Vehicle Operating As Classification <b>D CLASS</b>		Unit Type <b>AUTOMOBILE</b>	
	Vehicle Type <b>PASSENGER CAR</b>	Operating As Endorsements			
	Total Occs <b>1</b>	Train/Bus # Recorded	Total # Citations Issued <b>0</b>	Total Trailers <b>0</b>	Total HazMat Types <b>0</b>
	Insurance? <b>YES</b>	Direction Of Travel <b>NORTHBOUND</b>	<input checked="" type="checkbox"/> Pre Crash Tire Mark	Speed Limit <b>25</b>	Total Lanes <b>2</b>
	Most Harmful Event: Collision With <b>PARKED MOTOR VEHICLE</b>	Special Function <b>NO SPECIAL FUNCTION</b>		Emergency Motor Vehicle Use <b>NOT APPLICABLE</b>	
	Traffic Way <b>TWO-WAY, NOT DIVIDED</b>	Traffic Control <b>NO CONTROL</b>		Traffic Control Inoperative/Missing <b>NO</b>	
	Surface Type <b>BLACKTOP (BITUMINOUS)</b>	Road Curvature <b>CURVE LEFT</b>		Road Grade <b>LEVEL</b>	
	Truck Bus or HazMat <b>NO</b>				

Vehicle

<b>UNIT</b>	<b>VEHICLE</b>	License Plate Number <b>157UTV</b>	Plate Type <b>AUT - AUTOMOBILE</b>	St <b>WI</b>	Country of Issuance <b>UNITED STATES</b>	
		Vehicle Identification Number <b>4A3AC84H91E015401</b>	Make <b>MITSUBISHI</b>	Year <b>2001</b>	Model <b>ECLIPSE GT</b>	
		Color <b>SIL - SILVER (ALUMINUM)</b>	Body Style <b>2H - HATCHBACK 2 DOOR</b>		Bus Use	
		Initial Contact Point <b>02 - RIGHT SIDE FRONT</b>	Vehicle Damage <b>01 - RIGHT FRONT CORNER, 02 - RIGHT SIDE FRONT</b>			
		Extent Of Damage <b>FUNCTIONAL DAMAGE</b>				



WISCONSIN MOTOR VEHICLE  
CRASH REPORT

UNIT	Towed Due To Damage <b>NOT TOWED</b>		Vehicle Removed By <b>OPERATOR</b>		
	What Driver Was Doing <b>NEGOTIATING CURVE</b>		Vehicle Factors		
	Driver Prior Action Other		<b>NOT APPLICABLE</b>		
	Driver Actions <b>FAILURE TO CONTROL</b>				
01	01	Owner Name <b>DENIS CHARLES LA ROCCO (608) 475-1698</b>		Owner Address <b>117 THOMAS RD REEDSBURG, WI 53959 , US</b>	
		<b>Sequence Of Events</b>			
UNIT	01	Event <b>PARKED MOTOR VEHICLE</b>			
		Event			
		Event			
		Event			
UNIT	01	<b>Policy Holder</b>			
		Insurance Company <b>PEKIN-INS-CO</b>	Individual <b>DENIS LA ROCCO</b>		
UNIT	01	<b>Individual</b>			
		Driver <b>DENIS CHARLES LA ROCCO (608) 475-1698</b>	Citations Issued <b>0</b>	Sex <b>MALE</b>	
		Date of Birth <b>04/21/1968</b>		Race <b>WHITE</b>	
		Address <b>117 THOMAS RD REEDSBURG, WI 53959 , US</b>		Driver License Number <b>L6201636814107 STATE: WISCONSIN COUNTRY: UNITED STATES</b>	
UNIT	01	<b>Safety Equipment</b>		On Duty Crash	
		Safety Equipment <b>SHOULDER &amp; LAP BELT</b>			
		Row <b>01 - FRONT ROW</b>	Seat Position <b>07 - LEFT</b>		
		Helmet Use		Helmet Compliance	
Eye Protection		Tint Compliance			
UNIT	001	<b>Injury</b>		Airbag	
		Injury Severity <b>NO APPARENT INJURY</b>		<b>NON DEPLOYED</b>	
		Ejected <b>NOT EJECTED</b>	Ejection Path <b>NOT EJECTED/NOT APPLICABLE</b>	Trapped/Extricated <b>NOT TRAPPED</b>	
		Medical Transport <b>NOT TRANSPORTED</b>		EMS Agency Identifier	EMS Run #
Hospital		Date of Death	Time of Death		
<b>Distracted By</b>		Distracted By Source <b>NOT APPLICABLE (NOT DISTRACTED)</b>			
<b>Distracted By Action</b>		<b>NOT DISTRACTED</b>			


WISCONSIN MOTOR VEHICLE  
CRASH REPORT

<b>UNIT</b>	<b>INDIVIDUAL</b>	<b>Non Motorist</b>		Striking Unit #	Location		
		Prior Action					
		Action					
	Action Other					To/From School	
	<b>01</b>	<b>001</b>	<b>Drug &amp; Alcohol</b>		Suspected Alcohol Use <b>NO</b>	Suspected Drug Use <b>NO</b>	
			Alcohol Test Given <b>TEST NOT GIVEN</b>		Alcohol Test Type	Alcohol Test Results	
			Drug Test Given <b>TEST NOT GIVEN</b>		Drug Test Type	Drug Test Results	
			Drug Type				
			Individual Condition <b>APPEARED NORMAL</b>				

**Unit Summary**

<b>UNIT</b>	<b>02</b>	Unit Status <b>LEGALLY PARKED</b>		Vehicle Operating As Classification <b>D CLASS</b>		Unit Type <b>AUTOMOBILE</b>			
		Vehicle Type <b>PASSENGER CAR</b>					Operating As Endorsements		
		Total Occs <b>0</b>		Train/Bus # Recorded		Total # Citations Issued <b>0</b>		Total Trailers <b>0</b>	Total HazMat Types <b>0</b>
		Insurance? <b>YES</b>		Direction Of Travel <b>NORTHBOUND</b>		<input type="checkbox"/> Pre Crash Tire Mark		Speed Limit <b>25</b>	Total Lanes <b>2</b>
		Most Harmful Event: Collision With <b>MOTOR VEH IN TRANSPORT</b>			Special Function <b>NO SPECIAL FUNCTION</b>			Emergency Motor Vehicle Use <b>NOT APPLICABLE</b>	
		Traffic Way <b>TWO-WAY, NOT DIVIDED</b>			Traffic Control <b>NO CONTROL</b>			Traffic Control Inoperative/Missing <b>NO</b>	
		Surface Type <b>BLACKTOP (BITUMINOUS)</b>			Road Curvature <b>STRAIGHT</b>			Road Grade <b>LEVEL</b>	
		Truck Bus or HazMat <b>NO</b>							

<b>UNIT</b>	<b>VEHICLE</b>	<b>Vehicle</b>				
		License Plate Number <b>AKT7216</b>		Plate Type <b>AUT - AUTOMOBILE</b>	St <b>WI</b>	Country of Issuance <b>UNITED STATES</b>
		Vehicle Identification Number <b>1G11B5SL2EF284327</b>		Make <b>CHEVROLET</b>	Year <b>2014</b>	Model <b>MALIBU</b>
		Color <b>GRY - GRAY</b>		Body Style <b>SD - SEDAN</b>		Bus Use
		Initial Contact Point <b>07 - LEFT REAR CORNER</b>		Vehicle Damage		
		Extent Of Damage <b>FUNCTIONAL DAMAGE</b>		<b>06 - REAR, 07 - LEFT REAR CORNER</b>		
		Towed Due To Damage <b>NOT TOWED</b>		Vehicle Removed By <b>OWNER</b>		



9PL01884HJ  
CASE#R21-1847

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

UNIT	VEHICLE	What Driver Was Doing <b>LEGALLY PARKED</b>	Vehicle Factors
		Driver Prior Action Other	<b>NOT APPLICABLE</b>
		Driver Actions <b>NO CONTRIBUTING ACTION</b>	
		Owner Name <b>STACY M LINSCHIED (608) 963-9843</b>	Owner Address <b>64 THOMAS RD REEDSBURG, WI 53959 , US</b>
<b>Sequence Of Events</b>			
UNIT	VEHICLE	01 Event <b>MOTOR VEH IN TRANSPORT</b>	
		02 Event	
		03 Event	
		04 Event	
<b>Policy Holder</b>			
		Insurance Company <b>STATE-FARM-GENERAL-INS-CO</b>	Individual <b>STACY LINSCHIED</b>