

9PL01884HK
R21-01884

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

9PL01884HK

Document Number Override		Primary Crash Document #		Agency Crash Number		Investigating Officer/Deputy M. DUNSE	
Crash Date 02/18/2021		Crash Time 04:20 PM		Date Arrived 02/18/2021		Time Arrived 04:27 PM	
Date Notified 02/18/2021		Time Notified 04:24 PM		Total Units 02		Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure		<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)				<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

Diagram		Reconstruction By	
		Photos By M. DUNSE	
		Additional Information PHOTOS	

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 1 WAS STOPPED AT THE STOP SIGN ON MYRTLYE ST. AT E MAIN ST. UNIT 1 PROCEEDED THROUGH THE STOP SIGN ATTEMPTING TO MAKE A LEFT TURN ONTO E MAIN ST. (EASTBOUND) WHEN UNIT 2 WAS TRAVELING WESTBOUND ON E MAIN ST. UNIT 2 COLLIDED INTO UNIT 1 IN THE INTERSECTION OF E MAIN ST. @ MYRTLE ST. THERE WERE NO REPORTED INJURIES AND BOTH VEHICLES WERE ABLE TO BE MOVED FROM E MAIN ST ONTO MYRTLE ST. PRIOR TO LAW ENFORCEMENT ARRIVAL. UNIT 1 WAS ABLE TO BE DRIVEN FROM THE SCENE AND UNIT 2 WAS TOWED FROM THE SCENE DUE TO DAMAGES CAUSED BY THE CRASH. UNIT 1 DRIVER WAS CITED FOR FYR FROM A STOP SIGN AS UNIT 2 TRAVELING ON E MAIN ST. HAD THE RIGHT OF WAY AS IT IS NOT CONTROLLED BY ANY TRAFFIC LIGHTS/SIGNS AT THIS INTERSECTION. SEE FULL REPORT.

9PL01884HK
R21-01884

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

Location

ON MAIN ST/ STH23 EB 16 FT E OF STH23 EB IN THE CITY OF REEDSBURG IN SAUK COUNTY	Latitude 43.532538999	Longitude -90.00240923
	X Coordinate 257396.78125	Y Coordinate 4824335.5
	Structure Type	

Crash Scene

First Harmful Event MOTOR VEH IN TRANSPORT	First Harmful Event Location ON ROADWAY	
Manner of Collision 01 - ANGLE	Light Condition DAYLIGHT	
Road Surface Condition(s) WET	Roadway Factor(s) NONE	
Environment Factor(s) NONE		
Weather Condition(s) CLOUDY		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location INTERSECTION	Intersection Type T-INTERSECTION

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 1	Total Trailers 0	Total HazMat Types 0
	Insurance? YES	Direction Of Travel SOUTHBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 25	Total Lanes 4
	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way DIVIDED HWY W/O TRAFFIC BARRIER	Traffic Control STOP SIGN		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO				

Vehicle

UNIT	VEHICLE	License Plate Number AKG9800	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
		Vehicle Identification Number WDBAB23A8DB380843	Make MERCEDES BENZ	Year 1983	Model 240
		Color BGE - BEIGE	Body Style SD - SEDAN		Bus Use
		Initial Contact Point 10 - LEFT SIDE FRONT	Vehicle Damage 09 - LEFT SIDE MIDDLE		
		Extent Of Damage FUNCTIONAL DAMAGE			



9PL01884HK
R21-01884

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

UNIT VEHICLE	Towed Due To Damage NOT TOWED		Vehicle Removed By OPERATOR		
	What Driver Was Doing LEFT TURN		Vehicle Factors		
	Driver Prior Action Other		NOT APPLICABLE		
	Driver Actions FAILED TO YIELD RIGHT-OF-WAY				
01	Owner Name BRYCE DAVID HASWELL		Owner Address 527 4TH ST REEDSBURG, WI 53959 , US		
	Sequence Of Events				
01	01	Event MOTOR VEH IN TRANSPORT			
	02	Event LEFT TURN			
	03	Event			
	04	Event			
UNIT	Policy Holder				
	Insurance Company PROGRESSIVE-ADVANCED-INSURANCE-CO		Individual BRYCE HASWELL		
INDIVIDUAL	Individual				
	Driver BRYCE DAVID HASWELL		Citations Issued 1	Sex MALE	
			Date of Birth 04/21/2002	Race WHITE	
	Address 527 4TH ST REEDSBURG, WI 53959 , US		Driver License Number H2400640214105 STATE: WISCONSIN COUNTRY: UNITED STATES		
01	001	Safety Equipment		On Duty Crash	
				Safety Equipment SHOULDER & LAP BELT	
	Row 01 - FRONT ROW		Seat Position 07 - LEFT		
	Helmet Use		Helmet Compliance		
	Eye Protection		Tint Compliance		
001	001	Injury		Airbag	
		Injury Severity NO APPARENT INJURY		NON DEPLOYED	
	Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE	Trapped/Extricated NOT TRAPPED	
	Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #	
	Hospital		Date of Death	Time of Death	
Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)			
Distracted By Action		NOT DISTRACTED			

WISCONSIN MOTOR VEHICLE
CRASH REPORT


UNIT INDIVIDUAL 01 001	Non Motorist		Striking Unit #	Location	
	Prior Action				
	Action				
	Action Other			To/From School	
	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type	Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results	
	Drug Type				
	Individual Condition APPEARED NORMAL				
	Violations				
01	UTC Number BD876454	Issue To? 001	Statute Number 346.18(3)	Description FAIL/YIELD RIGHT/WAY FROM STOP SIGN	

Unit Summary

UNIT 02	Unit Status IN TRANSIT		Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR				Operating As Endorsements	
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0	
	Insurance? YES	Direction Of Travel WESTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 25	Total Lanes 4	
	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way DIVIDED HWY W/O TRAFFIC BARRIER		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT		Road Grade UPHILL	
	Truck Bus or HazMat NO					

Vehicle

UNIT 02	License Plate Number BID4DRT		Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
	Vehicle Identification Number JTDKARFU7G3025054		Make TOYOTA	Year 2016	Model PRIUS
	Color BLK - BLACK		Body Style HB - HATCHBACK		Bus Use
	Initial Contact Point 12 - FRONT				



9PL01884HK
R21-01884

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

UNIT VEHICLE	Vehicle Damage	
	Extent Of Damage DISABLING DAMAGE	12 - FRONT
	Towed Due To Damage TOWED DUE TO DISABLING DAMAGE	Vehicle Removed By
	What Driver Was Doing GOING STRAIGHT	Vehicle Factors
UNIT VEHICLE	Driver Prior Action Other	NOT APPLICABLE
	Driver Actions NO CONTRIBUTING ACTION	
02 02	Owner Name TAMMY LYN WELLS (608) 515-1677	Owner Address W9178 STATE ROAD 33 WONEWOC, WI 53968 , US
	Sequence Of Events	
01 02 03 04	Event MOTOR VEH IN TRANSPORT	
	Event	
	Event	
	Event	
UNIT INDIVIDUAL	Policy Holder	
	Insurance Company PARTNERS-MUTUAL-INS-CO	Individual TAMMY WELLS
02 002	Individual	
	Driver TAMMY LYN WELLS (608) 515-1677	Citations Issued 0
		Sex FEMALE
		Date of Birth 10/21/1964
	Race WHITE	
	Address W9178 STATE ROAD 33 WONEWOC, WI 53968 , US	Driver License Number W4208126488107 STATE: WISCONSIN COUNTRY: UNITED STATES
02 002	Safety Equipment	
	On Duty Crash	Safety Equipment
	Row 01 - FRONT ROW	Seat Position 07 - LEFT
	SHOULDER & LAP BELT	
	Helmet Use	Helmet Compliance
	Eye Protection	Tint Compliance
02 002	Injury	
	Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED
	Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE
	NOT TRAPPED	
	Medical Transport NOT TRANSPORTED	EMS Agency Identifier
	Hospital	EMS Run #
	Date of Death	Time of Death

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	INDIVIDUAL	Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)					
		Distracted By Action		NOT DISTRACTED					
		Non Motorist	Striking Unit #	Location					
			Prior Action						
		Action							
		Action Other				To/From School			
		02	002	Drug & Alcohol		Suspected Alcohol Use NO		Suspected Drug Use NO	
				Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type		Alcohol Test Results	
				Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	
				Drug Type					
Individual Condition APPEARED NORMAL									