

9PL0122XX8

R21-2885



WISCONSIN MOTOR VEHICLE CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

9PL0122XX8

Document Number Override		Primary Crash Document #		Agency Crash Number		Investigating Officer/Deputy W. BOTTEN	
Crash Date 03/15/2021		Crash Time 07:58 AM		Date Arrived 03/15/2021		Time Arrived 08:02 AM	
Date Notified 03/15/2021		Time Notified 07:58 AM		Total Units 03		Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold	
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type PRIVATE PROPERTY/PARKING LOT				<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

<p>Diagram</p> <p>Drawing not to scale</p>  <p>Reedsburg Physician's Group Parking Lot 2000 N Dewey</p> 	Reconstruction By
	Photos By 140
	Additional Information PHOTOS

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

OPERATOR OF UNIT 1 WAS CONDUCTING A U-TURN IN A PARKING LOT WHEN HIS BRAKES FAILED AND STRUCK UNITS 2 AND 3 CAUSING MINOR DAMAGE TO ALL THREE UNITS.

9PL0122XX8

R21-2885

WISCONSIN MOTOR VEHICLE CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

Location

ON 2000 N DEWEY AVE 272 FT N OF 19TH ST (HOUSE/BUILDING 2000) IN THE CITY OF REEDSBURG IN SAUK COUNTY	Latitude 43.549112674	Longitude -89.994580557
	X Coordinate 258095.734375	Y Coordinate 4826153
	Structure Type HOUSE/BUILDING	


Crash Scene

First Harmful Event MOTOR VEH IN TRANSPORT	First Harmful Event Location OFF ROADWAY, LOCATION UNKNOWN	
Manner of Collision 02 - FRONT TO FRONT	Light Condition DAYLIGHT	
Road Surface Condition(s) DRY	Roadway Factor(s) NONE	
Environment Factor(s) NONE		
Weather Condition(s) CLOUDY		
Animal Type	Relation To Trafficway NON TRAFFICWAY - PARKING LOT	
Crash Classification - Location PRIVATE PROPERTY	Crash Classification - Jurisdiction PRIVATE PROPERTY	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS	Unit Type AUTOMOBILE		
	Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0
	Insurance? NO	Direction Of Travel NOT ON ROADWAY	<input type="checkbox"/> Pre CrashTire Mark	Speed Limit N/A	Total Lanes
	Most Harmful Event: Collision With PARKED MOTOR VEHICLE	Special Function NO SPECIAL FUNCTION	Emergency Motor Vehicle Use NOT APPLICABLE		
	Traffic Way PARKING LOT OR PRIVATE PROPERTY	Traffic Control NO CONTROL	Traffic Control Inoperative/Missing NO		
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT	Road Grade LEVEL		
	Truck Bus or HazMat NO				

UNIT	VEHICLE	Vehicle			
		License Plate Number	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
		Vehicle Identification Number 4G2JB32T2XB200113	Make PONTIAC	Year 1999	Model SUNFIRE GT
		Color BLK - BLACK	Body Style CV - CONVERTIBLE		Bus Use
		Initial Contact Point 12 - FRONT	Vehicle Damage 01 - RIGHT FRONT CORNER, 11 - LEFT FRONT CORNER		
Extent Of Damage MINOR DAMAGE					



9PL0122XX8

R21-2885

WISCONSIN MOTOR VEHICLE CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

UNIT VEHICLE	Towed Due To Damage TOWED BUT NOT DUE TO DISABLING DAMAG		Vehicle Removed By	
	What Driver Was Doing U TURN		Vehicle Factors	
	Driver Prior Action Other		BRAKES	
	Driver Actions NO CONTRIBUTING ACTION			
01	01	Owner Name ROBERT MARVIN WESOLOSKI (608) 633-3711		Owner Address 1100 19TH #2 REEDSBURG, WI 53959 , US
Sequence Of Events				
01	Event PARKED MOTOR VEHICLE			
02	Event			
03	Event			
04	Event			
Individual				
UNIT INDIVIDUAL	Driver ROBERT MARVIN WESOLOSKI (608) 633-3711		Citations Issued 0	Sex MALE
	Address 1100 19TH #2 REEDSBURG, WI 53959 , US		Date of Birth 09/29/1989	Race WHITE
			Driver License Number W2427738934900	STATE: WISCONSIN COUNTRY: UNITED STATES
Safety Equipment				
		On Duty Crash	Safety Equipment	
Row 01 - FRONT ROW		Seat Position 07 - LEFT	SHOULDER & LAP BELT	
Helmet Use		Helmet Compliance		
Eye Protection		Tint Compliance		
01	001	Injury	Injury Severity NO APPARENT INJURY	Airbag NON DEPLOYED
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED
Medical Transport NOT TRANSPORTED		EMS Agency Identifier		EMS Run #
Hospital		Date of Death		Time of Death
Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)		
Distracted By Action		NOT DISTRACTED		
Non Motorist				
		Striking Unit #	Location	

9PL0122XX8
R21-2885

WISCONSIN MOTOR VEHICLE
CRASH REPORT


REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

UNIT	INDIVIDUAL	Prior Action				
		Action				
		Action Other			To/From School	
	01	001	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO
			Alcohol Test Given TEST NOT GIVEN	Alcohol Test Type		Alcohol Test Results
			Drug Test Given TEST NOT GIVEN	Drug Test Type	Drug Test Results	
			Drug Type			
			Individual Condition APPEARED NORMAL			

Unit Summary

UNIT	02	Unit Status LEGALLY PARKED	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
		Vehicle Type (SPORT) UTILITY VEHICLE			Operating As Endorsements	
	Total Occs 0	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0	
	Insurance? YES	Direction Of Travel NOT ON ROADWAY	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit N/A	Total Lanes	
	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way PARKING LOT OR PRIVATE PROPERTY		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO					

UNIT	VEHICLE	Vehicle			
		License Plate Number 670TDF	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
		Vehicle Identification Number 1GKDT13W3X2531467	Make GENERAL MOTORS COR	Year 1999	Model JIMMY
		Color RED - RED	Body Style UT - SPORT UTILITY VEHICLE		Bus Use
		Initial Contact Point 01 - RIGHT FRONT CORNER	Vehicle Damage		
		Extent Of Damage MINOR DAMAGE	01 - RIGHT FRONT CORNER		
		Towed Due To Damage NOT TOWED	Vehicle Removed By OPERATOR		
		What Driver Was Doing LEGALLY PARKED			



9PL0122XX8

R21-2885

WISCONSIN MOTOR VEHICLE CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

UNIT VEHICLE	Driver Prior Action Other		Vehicle Factors
	Driver Actions		NOT APPLICABLE
	NO CONTRIBUTING ACTION		
02	Owner Name	Owner Address	
	RHONDA M HANSEN	1607 HEMLOCK DR APT A REEDSBURG, WI 53959 , US	
Sequence Of Events			
01 02 03 04	Event	MOTOR VEH IN TRANSPORT	
	Event		
	Event		
	Event		
UNIT	Policy Holder		
	Insurance Company	Individual	
	PROGRESSIVE-ADVANCED-INSURANCE-CO	RHONDA HANSEN	

Unit Summary

UNIT 03	Unit Status	Vehicle Operating As Classification	Unit Type	
	LEGALLY PARKED	D CLASS	AUTOMOBILE	
UNIT 03	Vehicle Type	Operating As Endorsements		
	(SPORT) UTILITY VEHICLE			
	Total Occs	Train/Bus # Recorded	Total # Citations Issued	Total Trailers
	0		0	0
	Insurance?	Direction Of Travel	<input type="checkbox"/> Pre CrashTire Mark	Speed Limit
	YES	NOT ON ROADWAY		N/A
	Total Lanes	0		
Most Harmful Event: Collision With	Special Function	Emergency Motor Vehicle Use		
MOTOR VEH IN TRANSPORT	NO SPECIAL FUNCTION	NOT APPLICABLE		
Traffic Way	Traffic Control	Traffic Control Inoperative/Missing		
PARKING LOT OR PRIVATE PROPERTY	NO CONTROL	NO		
Surface Type	Road Curvature	Road Grade		
BLACKTOP (BITUMINOUS)	STRAIGHT	LEVEL		
Truck Bus or HazMat	NO			

UNIT 03	Vehicle			
	License Plate Number	Plate Type	St	Country of Issuance
03	343XYX	AUT - AUTOMOBILE	WI	UNITED STATES
	Vehicle Identification Number	Make	Year	Model
VEHICLE	JTMBK31VX95077828	TOYOTA	2009	RAV4 LTD
	Color	Body Style	Bus Use	
WHI - WHITE	LL - CARRYALL			
Initial Contact Point	Vehicle Damage			
11 - LEFT FRONT CORNER	11 - LEFT FRONT CORNER			
Extent Of Damage	Vehicle Removed By			
MINOR DAMAGE	OPERATOR			
Towed Due To Damage	NOT TOWED			

9PL0122XX8

R21-2885

WISCONSIN MOTOR VEHICLE CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

UNIT	VEHICLE	What Driver Was Doing LEGALLY PARKED	Vehicle Factors
		Driver Prior Action Other	NOT APPLICABLE
		Driver Actions NO CONTRIBUTING ACTION	
		Owner Name DAVID DUANE WEBBER (608) 495-0476	Owner Address S1049 SMITH RD LA VALLE, WI 53941 , US
Sequence Of Events			
UNIT	VEHICLE	01	Event MOTOR VEH IN TRANSPORT
		02	Event
		03	Event
		04	Event
Policy Holder			
		Insurance Company RURAL-MUTUAL-INS-CO-(ATTN:-CLAIMS-DEPT)	Individual DAVID WEBBER