

9PL00K8HL6
R21-4924

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

9PL00K8HL6

Document Number Override		Primary Crash Document #		Agency Crash Number		Investigating Officer/Deputy J. HOEGE	
Crash Date 05/05/2021		Crash Time 11:33 AM		Date Arrived 05/05/2021		Time Arrived 11:35 AM	
Date Notified 05/05/2021		Time Notified 11:33 AM		Total Units 02		Total Injured 01	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input checked="" type="checkbox"/> Lane Closure		<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)				<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

Diagram		Reconstruction By REEDSBURG POLICE DEPARTMENT	
		Photos By J. HOEGE T. KNUTH	
		Additional Information PHOTOS, RECONSTRUCTION	

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

U1 LEFT A DRIVEWAY TO CROSS THE HIGHWAY. U2 STRUCK U1. U1 DID NOT REPORT INJURY WHILE U2 WAS TRANSPORTED TO UW MADISON FOR TREATMENT. SEE REPORT FOR FULL DETAILS.

9PL00K8HL6
R21-4924

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

Location

ON VIKING DR 493 FT N OF STH23 WB IN THE CITY OF REEDSBURG IN SAUK COUNTY	Latitude 43.533825425	Longitude -89.984637852
	X Coordinate 258837.96875	Y Coordinate 4824426.5
	Structure Type NO STRUCTURE	

Crash Scene

First Harmful Event MOTOR VEH IN TRANSPORT		First Harmful Event Location ON ROADWAY	
Manner of Collision 01 - ANGLE		Light Condition DAYLIGHT	
Road Surface Condition(s) DRY		Roadway Factor(s) NONE	
Environment Factor(s) NONE			
Weather Condition(s) CLEAR			
Animal Type		Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY		Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land		Access Control PARTIAL CONTROL	Special Study
Within Interchange Area NO	Junction Location DRIVEWAY ACCESS-RELATED	Intersection Type NOT AN INTERSECTION	
Closure Type LANE CLOSURE		Reasons for Closure	
Date Initial Lane/Rd Closed 05/05/2021	Time Initial Lane/Rd Closed 11:33 AM	LAW ENFORCEMENT, FIRE/EMS	
Date All Lanes Open 05/05/2021	Time All Lanes Open 12:03 PM		
Date Scene Cleared 05/05/2021	Time Scene Cleared 12:08 PM		


Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE		
	Vehicle Type PASSENGER CAR	Operating As Endorsements				
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 1	Total Trailers 0	Total HazMat Types 0	
	Insurance? YES	Direction Of Travel EASTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 25	Total Lanes 4	
	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO					
	01	Vehicle				
		License Plate Number AEJ9390		Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
Vehicle Identification Number 5NPDH4AE3GH725312		Make HYUNDAI	Year 2016	Model ELANTRA		

9PL00K8HL6
R21-4924

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

UNIT VEHICLE	Color WHI - WHITE	Body Style 4D - 4DR	Bus Use
	Initial Contact Point 03 - RIGHT SIDE MIDDLE	Vehicle Damage 01 - RIGHT FRONT CORNER, 02 - RIGHT SIDE FRONT, 03 - RIGHT SIDE MIDDLE, 04 - RIGHT SIDE REAR, 05 - RIGHT REAR CORNER	
	Extent Of Damage DISABLING DAMAGE		
	Towed Due To Damage TOWED DUE TO DISABLING DAMAGE		
	What Driver Was Doing ENTERING TRAFFIC LANE	Vehicle Factors	
	Driver Prior Action Other	NOT APPLICABLE	
UNIT VEHICLE	Driver Actions FAILED TO YIELD RIGHT-OF-WAY, LOOKED BUT DID NOT SEE		
	Owner Name EDWARD E SMITH (608) 495-6093	Owner Address 840 N GROVE ST REEDSBURG, WI 53959 , US	
UNIT 01	Sequence Of Events		
	Event MOTOR VEH IN TRANSPORT		
	Event MOTOR VEH IN TRANSPORT		
	Event MOTOR VEH IN TRANSPORT		
	Event MOTOR VEH IN TRANSPORT		
UNIT INDIVIDUAL	Policy Holder		
	Insurance Company AMERICAN-FAMILY-INS-CO	Individual EDWARD SMITH	
	Individual		
UNIT INDIVIDUAL	Driver EDWARD E SMITH (608) 495-6093	Citations Issued 1	Sex MALE
		Date of Birth 09/23/1937	Race WHITE
	Address 840 N GROVE ST REEDSBURG, WI 53959 , US	Driver License Number S5302253734306 STATE: WISCONSIN COUNTRY: UNITED STATES	
	Safety Equipment		
	On Duty Crash	Safety Equipment	
Row 01 - FRONT ROW	Seat Position 07 - LEFT	SHOULDER & LAP BELT	
Helmet Use		Helmet Compliance	
Eye Protection		Tint Compliance	
UNIT 01	Injury	Injury Severity NO APPARENT INJURY	Airbag DEPLOYED-SIDE
	Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE	Trapped/Extricated NOT TRAPPED
	Medical Transport NOT TRANSPORTED	EMS Agency Identifier	EMS Run #

UNIT	Hospital		Date of Death		Time of Death	
	Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)			
	Distracted By Action NOT DISTRACTED					
	Non Motorist		Striking Unit #		Location	
	Prior Action					
	Action					
	Action Other					
	To/From School					
	Drug & Alcohol		Suspected Alcohol Use NO		Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type		Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	
	Drug Type					
	Individual Condition APPEARED NORMAL					
	Violations					
	01	001	01	UTC Number AP279063	Issue To? 001	Statute Number 346.18(5)


Unit Summary

UNIT	02	Unit Status IN TRANSIT		Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR		Operating As Endorsements				
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0		
	Insurance? YES	Direction Of Travel NORTHBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 25	Total Lanes 4		
	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE		
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO		
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT		Road Grade LEVEL		
	Truck Bus or HazMat NO						
	Vehicle						
	License Plate Number 173PMK			Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	

9PL00K8HL6
R21-4924

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

02 UNIT VEHICLE	Vehicle Identification Number 1G4HD57218U166720		Make BUICK	Year 2008	Model LUCERNE	
	Color GRY - GRAY		Body Style 4D - 4DR		Bus Use	
	Initial Contact Point 12 - FRONT		Vehicle Damage 01 - RIGHT FRONT CORNER, 02 - RIGHT SIDE FRONT, 11 - LEFT FRONT CORNER, 12 - FRONT			
	Extent Of Damage DISABLING DAMAGE					
	Towed Due To Damage TOWED DUE TO DISABLING DAMAGE					
	What Driver Was Doing GOING STRAIGHT		Vehicle Factors NOT APPLICABLE			
Driver Prior Action Other						
02 UNIT VEHICLE	Driver Actions LOOKED BUT DID NOT SEE					
	Owner Name MARLENE JEAN FEARING (608) 768-4604		Owner Address 2061 FAWN VALLEY CT REEDSBURG, WI 53959 , US			
Sequence Of Events						
02 UNIT VEHICLE	Event MOTOR VEH IN TRANSPORT					
	Event MOTOR VEH IN TRANSPORT					
	Event CURB					
	Event UTILITY POLE					
02 UNIT VEHICLE	Policy Holder					
	Insurance Company AMERICAN-FAMILY-INS-CO		Individual MARLENE FEARING			
02 UNIT INDIVIDUAL	Individual		Citations Issued 0		Sex FEMALE	
	Driver MARLENE JEAN FEARING (608) 768-4604		Date of Birth 05/31/1932		Race WHITE	
	Address 2061 FAWN VALLEY CT REEDSBURG, WI 53959 , US		Driver License Number F6525503269109 STATE: WISCONSIN COUNTRY: UNITED STATES			
02 UNIT INDIVIDUAL	Safety Equipment		On Duty Crash			
	Row 01 - FRONT ROW		Seat Position 07 - LEFT		Safety Equipment SHOULDER & LAP BELT	
	Helmet Use		Helmet Compliance			
	Eye Protection		Tint Compliance			
	Injury		Injury Severity SUSPECTED SERIOUS INJUR		Airbag DEPLOYED-FRONT	
Ejected NOT EJECTED		Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED		

