

9PL013B00G
R21-5008

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

9PL013B00G

Document Number Override		Primary Crash Document #		Agency Crash Number R21-5008		Investigating Officer/Deputy J. HOEGE	
Crash Date 05/07/2021		Crash Time 11:05 AM		Date Arrived 05/07/2021		Time Arrived 11:08 AM	
Date Notified 05/07/2021		Time Notified 11:07 AM		Total Units 02		Total Injured 01	Total Killed 00
<input type="checkbox"/> On Emergency		<input type="checkbox"/> Hit and Run		<input checked="" type="checkbox"/> Lane Closure		<input type="checkbox"/> Work Zone	
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)		<input type="checkbox"/> Amended		<input type="checkbox"/> Secondary Crash	
<input type="checkbox"/> Trailer or Towed		<input type="checkbox"/> Reporting Threshold					

Description

Diagram		Reconstruction By REEDSBURG POLICE DEPARTMENT	
<p>North Ave</p> <p>8th St</p> <p>Myrtle St</p> <p>527 8th St</p> <p>U1</p> <p>U2</p> <p>STOP</p> <p>Not to scale</p>		Photos By J. HOEGE	
		Additional Information NONE, PHOTOS, RECONSTRUCTION	

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

SEE R21-5008 FOR FULL DETAILS. U2 WAS LEGALLY PARKED WHEN U1 STRUCK U2 PUSHING IT UP ONTO THE CURB. BOTH VEHICLES TOWED FROM THE SCENE

9PL013B00G
R21-5008

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

Location

ON 8TH ST 134 FT E OF N PINE ST IN THE CITY OF REEDSBURG IN SAUK COUNTY	Latitude 43.539667278	Longitude -90.003718993
	X Coordinate 257319.5625	Y Coordinate 4825131
	Structure Type	

Crash Scene

First Harmful Event MOTOR VEH IN TRANSPORT		First Harmful Event Location ON ROADWAY	
Manner of Collision 03 - FRONT TO REAR		Light Condition DAYLIGHT	
Road Surface Condition(s) DRY		Roadway Factor(s) NONE	
Environment Factor(s) NONE			
Weather Condition(s) CLEAR			
Animal Type		Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY		Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land		Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION	
Closure Type CLOSURE-ONE DIRECTION		Reasons for Closure LAW ENFORCEMENT, TOW TRUCK, FIRE/EMS	
Date Initial Lane/Rd Closed 05/07/2021	Time Initial Lane/Rd Closed 11:07 AM	Date Scene Cleared 05/07/2021	
Date All Lanes Open 05/07/2021	Time All Lanes Open 11:21 AM		


Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0
	Insurance? YES	Direction Of Travel WESTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 25	Total Lanes 2
	Most Harmful Event: Collision With PARKED MOTOR VEHICLE		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT		Road Grade DOWNHILL
	Truck Bus or HazMat NO				
01	Vehicle				
	License Plate Number AHY8000		Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
01	Vehicle Identification Number 1G1ZJ57B694141436		Make CHEVROLET	Year 2009	Model MALIBU

9PL013B00G
R21-5008

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

UNIT VEHICLE	Color BLK - BLACK	Body Style SD - SEDAN	Bus Use	
	Initial Contact Point 01 - RIGHT FRONT CORNER	Vehicle Damage 01 - RIGHT FRONT CORNER, 02 - RIGHT SIDE FRONT, 12 - FRONT		
	Extent Of Damage DISABLING DAMAGE			
	Towed Due To Damage TOWED DUE TO DISABLING DAMAGE			Vehicle Removed By
	What Driver Was Doing GOING STRAIGHT			Vehicle Factors
Driver Prior Action Other	STEERING			
UNIT VEHICLE	Driver Actions NO CONTRIBUTING ACTION			
	Owner Name ANGELINA CHRISTINA BONDI (608) 432-6255	Owner Address S1121 LYNDON RD WISCONSIN DELLS, WI 53965 , US		
UNIT 01	Sequence Of Events			
	Event 01 MOTOR VEH IN TRANSPORT			
	Event 02 MOTOR VEH IN TRANSPORT			
	Event 03 MOTOR VEH IN TRANSPORT			
	Event 04 PARKED MOTOR VEHICLE			
UNIT 01	Policy Holder			
	Insurance Company STATE-FARM-GENERAL-INS-CO	Individual ANGELINA BONDI		
UNIT INDIVIDUAL	Individual			
	Driver ANGELINA CHRISTINA BONDI (608) 432-6255	Citations Issued 0	Sex FEMALE	
		Date of Birth 05/28/2002	Race WHITE	
	Address S1121 LYNDON RD WISCONSIN DELLS, WI 53965 , US	Driver License Number B5300030268804 STATE: WISCONSIN COUNTRY: UNITED STATES		
UNIT 01	Safety Equipment			
	On Duty Crash		Safety Equipment	
	Row 01 - FRONT ROW	Seat Position 07 - LEFT	SHOULDER & LAP BELT	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	Injury	Injury Severity SUSPECTED MINOR INJURY	Airbag NON DEPLOYED	
UNIT 001	Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE	Trapped/Extricated NOT TRAPPED	
	Medical Transport EMS GROUND		EMS Agency Identifier 601024	
			EMS Run #	

UNIT	Hospital REEDSBURG AREA MED CTR		Date of Death		Time of Death	
	Distracted By		Distracted By Source UNKNOWN			
	Distracted By Action UNKNOWN					
	Non Motorist		Striking Unit #		Location	
	Prior Action					
	Action					
	Action Other					To/From School
	Drug & Alcohol		Suspected Alcohol Use NO		Suspected Drug Use NO	
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type		Alcohol Test Results	
	Drug Test Given TEST NOT GIVEN		Drug Test Type		Drug Test Results	
Drug Type						
Individual Condition APPEARED NORMAL						

Unit Summary

UNIT	Unit Status LEGALLY PARKED		Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type (SPORT) UTILITY VEHICLE				Operating As Endorsements	
	Total Occs 0		Train/Bus # Recorded		Total # Citations Issued 0	
	Total Trailers 0		Total HazMat Types 0		Insurance? YES	
	Direction Of Travel WESTBOUND		<input type="checkbox"/> Pre Crash Tire Mark		Speed Limit 25	
	Total Lanes 2		Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT		Special Function NO SPECIAL FUNCTION	
	Emergency Motor Vehicle Use NOT APPLICABLE		Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL	
	Traffic Control Inoperative/Missing NO		Surface Type BLACKTOP (BITUMINOUS)		Road Grade DOWNHILL	
	Road Curvature STRAIGHT		Truck Bus or HazMat NO			

Vehicle

02	License Plate Number REGI92		Plate Type PAK - PACKER		St WI	Country of Issuance UNITED STATES
	Vehicle Identification Number 5GAKVBKD1HJ131466		Make BUICK		Year 2017	Model ENCLAVE
	Color MAR - MAROON (BURGUNDY)		Body Style UT - SPORT UTILITY VEHICLE			Bus Use

9PL013B00G
R21-5008

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

UNIT	VEHICLE	Initial Contact Point 07 - LEFT REAR CORNER	Vehicle Damage 06 - REAR, 07 - LEFT REAR CORNER, 08 - LEFT SIDE REAR	
		Extent Of Damage DISABLING DAMAGE		
		Towed Due To Damage TOWED DUE TO DISABLING DAMAGE	Vehicle Removed By	
		What Driver Was Doing LEGALLY PARKED	Vehicle Factors	
		Driver Prior Action Other	NOT APPLICABLE	
UNIT	VEHICLE	Driver Actions NO CONTRIBUTING ACTION		
		Owner Name KIM MARIE SCHULZ (608) 963-8556	Owner Address 527 8TH ST REEDSBURG, WI 53959 , US	
		Sequence Of Events		
02	02	01 Event MOTOR VEH IN TRANSPORT		
		02 Event MOTOR VEH IN TRANSPORT		
		03 Event MOTOR VEH IN TRANSPORT		
		04 Event CURB		
UNIT	02	Policy Holder		
		Insurance Company OWNERS-INS-CO	Individual KIM SCHULZ	