

9PL010TWSW

R21-05859

WISCONSIN MOTOR VEHICLE CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

9PL010TWSW

Document Number Override, Primary Crash Document #, Agency Crash Number, Investigating Officer/Deputy B. CUTRELL, Crash Date 05/27/2021, Crash Time 04:09 PM, Date Arrived 05/27/2021, Time Arrived 04:09 PM, Date Notified 05/27/2021, Time Notified 04:09 PM, Total Units 02, Total Injured 00, Total Killed 00, On Emergency, Hit and Run, Lane Closure, Work Zone, Trailer or Towed, Reporting Threshold, Government Property, Active School Zone, School Bus Related NO, Tags, Reportable, Crash Type DT4000 (STANDARD CRASH), Amended, Secondary Crash

Description

Diagram, Reconstruction By, Photos By, Additional Information NONE

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.
BLAKELEE'S VEHICLE WAS PARKED WESTBOUND ON K ST NEAR THE ENTRANCE TO ST VINCENT'S. BLAKE SAID THAT AROUND 1500 A FRIEND WENT TO CHANGE THE TIRE ON THE VEHICLE. WHEN THE FRIEND CAME BACK ABOUT 45 MINUTES LATER. THE FRONT BUMPER WAS TORE OFF AND APPEARED THAT SOMEONE HAD HIT IT. BLAKELEE JUST WANTED IT DOCUMENTED THAT THE ACCIDENT HAD OCCURRED. I CHECKED AND NO CAMERAS WERE OBSERVED IN THE AREA OF WHERE THE CRASH OCCURRED. NOTHING FURTHER. BTC153

9PL010TWSW
R21-05859

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

Location

ON K ST 190 FT W OF STH23 EB IN THE CITY OF REEDSBURG IN SAUK COUNTY	Latitude 43.525299638	Longitude -90.019604572
	X Coordinate 255978.078125	Y Coordinate 4823581.5
	Structure Type NO STRUCTURE	


Crash Scene

First Harmful Event MOTOR VEH IN TRANSPORT	First Harmful Event Location ROADSIDE	
Manner of Collision 07 - SIDESWIPE/SAME DIRECTION	Light Condition DAYLIGHT	
Road Surface Condition(s) WET	Roadway Factor(s)	
Environment Factor(s)		
Weather Condition(s) RAIN		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location NON-JUNCTION	Intersection Type NOT AN INTERSECTION

Unit Summary

UNIT 01	Unit Status LEGALLY PARKED		Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE	
	Vehicle Type PASSENGER CAR				Operating As Endorsements	
	Total Occs 0	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0	
	Insurance? NOT APPLICABLE	Direction Of Travel WESTBOUND	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit 25	Total Lanes 2	
	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT		Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)		Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO					

UNIT 01 VEHICLE	Vehicle					
	License Plate Number AKG2063		Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES	
	Vehicle Identification Number KMHNC46C99U377743		Make HYUNDAI	Year 2009	Model ACCENT	
	Color BLU - BLUE		Body Style SD - SEDAN		Bus Use	
	Initial Contact Point 11 - LEFT FRONT CORNER		Vehicle Damage 01 - RIGHT FRONT CORNER, 11 - LEFT FRONT CORNER, 12 - FRONT			
Extent Of Damage MINOR DAMAGE						



9PL010TWSW

R21-05859

WISCONSIN MOTOR VEHICLE CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

UNIT VEHICLE	Towed Due To Damage NOT TOWED	Vehicle Removed By OPERATOR
	What Driver Was Doing LEGALLY PARKED	Vehicle Factors
	Driver Prior Action Other	
	Driver Actions NO CONTRIBUTING ACTION	
01	Owner Name BLAKELEE ALEXANDER WILCOX	Owner Address E5746 IRISH VALLEY RD PLAIN, WI 53577 , US
Sequence Of Events		
01	Event MOTOR VEH IN TRANSPORT	
02	Event	
03	Event	
04	Event	

Unit Summary

UNIT 02	Unit Status HIT AND RUN	Vehicle Operating As Classification D CLASS	Unit Type AUTOMOBILE		
	Vehicle Type PASSENGER CAR	Operating As Endorsements			
	Total Occs 0	Train/Bus # Recorded	Total # Citations Issued 0	Total Trailers 0	Total HazMat Types 0
	Insurance? UNKNOWN	Direction Of Travel UNKNOWN	<input type="checkbox"/> Pre CrashTire Mark	Speed Limit	Total Lanes
	Most Harmful Event: Collision With PARKED MOTOR VEHICLE		Special Function UNKNOWN	Emergency Motor Vehicle Use UNKNOWN	
	Traffic Way UNKNOWN		Traffic Control UNKNOWN	Traffic Control Inoperative/Missing UNKNOWN	
	Surface Type UNKNOWN		Road Curvature UNKNOWN	Road Grade UNKNOWN	
	Truck Bus or HazMat NO				

UNIT VEHICLE 02	Vehicle			
	License Plate Number	Plate Type	St	Country of Issuance
	Vehicle Identification Number	Make	Year	Model
	Color	Body Style	Bus Use	
	Initial Contact Point 99 - UNKNOWN	Vehicle Damage		
	Extent Of Damage	99		
Towed Due To Damage NOT TOWED	Vehicle Removed By OPERATOR			
What Driver Was Doing UNKNOWN				

9PL010TWSW

R21-05859

WISCONSIN MOTOR VEHICLE CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

UNIT			Vehicle Factors	
	Driver Prior Action Other		UNKNOWN	
	Driver Actions		UNKNOWN	
	Owner Name		Owner Address	
VEHICLE	02	Sequence Of Events		
		01	Event	
	02	Event		
	03	Event		
	04	Event		