

9PL01884HQ  
R21-08025

# WISCONSIN MOTOR VEHICLE CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

9PL01884HQ

Document Number Override		Primary Crash Document #		Agency Crash Number		Investigating Officer/Deputy <b>B. CUTRELL</b>	
Crash Date <b>07/18/2021</b>		Crash Time <b>03:00 PM</b>		Date Arrived <b>07/22/2021</b>		Time Arrived <b>02:53 PM</b>	
Date Notified <b>07/22/2021</b>		Time Notified <b>02:53 PM</b>		Total Units <b>02</b>		Total Injured <b>00</b>	Total Killed <b>00</b>
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold	
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related <b>NO</b>		Tags	
<input type="checkbox"/> Reportable		Crash Type <b>PRIVATE PROPERTY/PARKING LOT</b>				<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

## Description

Diagram	Reconstruction By
	Photos By <b>REPD153</b>
	Additional Information <b>PHOTOS, SURVEILLANCE VIDEO</b>

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

ON 7/18 UNIT1 WAS LEGALLY PARKED IN THE VIKING PARKING LOT. UNIT1 DRIVER DID NOT NOTICE DAMAGE UNTIL NEXT DAY AND HAD ONLY NOTICED THE DAMAGE AFTER VISITING VIKING GROCERY. THE DAMAGE WAS TO THE DRIVER SIDE REAR QUARTER OF THE LEXUS. HE THEN OBTAINED SURVEILLANCE VIDEO FROM THE STORE.

I WAS GIVEN THE VIDEO WHICH I REVIEWED AND NOTED THAT UNIT2 ENTERED THE PARKING LOT, WENT TO PARK NEXT TO UNIT1 ON IT'S DRIVER SIDE AND APPEARED TO MAKE CONTACT WITH UNIT1. THE VEHICLE THEN STOPPED. A VEHICLE WAS PARKED IN FRONT OF THE PARKING STALL UNIT2 HAD ATTEMPTED TO PARK IN SO UNIT2 BACKED UP, THEN WENT TO THE NEXT ROW AND PARKED. THE DRIVER OF UNIT2 IS THEN SEEN GETTING OUT OF THEIR VEHICLE AND STANDING IN FRONT OF THE PASSENGER SIDE, AND LOOKING AT WHERE DAMAGE WOULD HAVE OCCURRED. SHE THEN GOES INTO THE STORE, SHOPS AND COMES BACK TO HER VEHICLE AND LEAVES. AT NOT TIME DID SHE ATTEMPT TO CONTACT THE OWNER OF UNIT1 OR LAW ENFORCEMENT.

SHE MAINTAINED THAT SHE DID NOT KNOW THERE WAS DAMAGE, EVEN THOUGH WHEN SHE GOT OUT OF HER CAR, SHE WAS LOOKING AT THE AREA

9PL01884HQ  
R21-08025

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

WHERE THE DAMAGE WAS OBSERVED FOR AN EXTENDED AMOUNT OF TIME.

UNIT2 DRIVER DENIED EVER KNOWING SHE HIT UNIT1. UNIT2 DRIVER WAS CITED FOR DCMV AND FOUND TO BE AT FAULT.

NOTHING FURTHER.  
BTC153

**Location**

<b>PARKING LOT</b> <b>VIKING DR LOT 150</b> <b>(HOUSE/BUILDING 150)</b>  <b>IN THE CITY OF REEDSBURG</b> <b>IN SAUK COUNTY</b>	Latitude <b>43.533789299</b>	Longitude <b>-89.983048604</b>
	X Coordinate <b>258966.234375</b>	Y Coordinate <b>4824418</b>
	Structure Type <b>HOUSE/BUILDING</b>	

**Crash Scene**

First Harmful Event <b>PARKED MOTOR VEHICLE</b>	First Harmful Event Location <b>OFF ROADWAY, LOCATION UNKNOWN</b>	
Manner of Collision <b>01 - ANGLE</b>	Light Condition <b>DAYLIGHT</b>	
Road Surface Condition(s) <b>DRY</b>	Roadway Factor(s)  <b>NONE</b>	
Environment Factor(s) <b>NONE</b>		
Weather Condition(s) <b>CLEAR</b>		
Animal Type	Relation To Trafficway <b>NON TRAFFICWAY - PARKING LOT</b>	
Crash Classification - Location <b>PUBLIC PROPERTY</b>	Crash Classification - Jurisdiction <b>NO SPECIAL JURISDICTION</b>	
Tribal Land	Access Control <b>NO CONTROL</b>	Special Study
Within Interchange Area <b>NO</b>	Junction Location <b>NON-JUNCTION</b>	Intersection Type <b>NOT AN INTERSECTION</b>

**Unit Summary**

<b>UNIT</b>	Unit Status <b>LEGALLY PARKED</b>	Vehicle Operating As Classification <b>D CLASS</b>	Unit Type <b>AUTOMOBILE</b>		
	Vehicle Type <b>PASSENGER CAR</b>	Operating As Endorsements			
	Total Occs <b>0</b>	Train/Bus # Recorded	Total # Citations Issued <b>0</b>	Total Trailers <b>0</b>	Total HazMat Types <b>0</b>
	Insurance? <b>YES</b>	Direction Of Travel <b>NOT ON ROADWAY</b>	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit	Total Lanes
	Most Harmful Event: Collision With <b>MOTOR VEH IN TRANSPORT</b>	Special Function <b>NO SPECIAL FUNCTION</b>	Emergency Motor Vehicle Use <b>NOT APPLICABLE</b>		
	Traffic Way <b>PARKING LOT OR PRIVATE PROPERTY</b>	Traffic Control <b>NO CONTROL</b>	Traffic Control Inoperative/Missing <b>NO</b>		
	Surface Type <b>BLACKTOP (BITUMINOUS)</b>	Road Curvature <b>STRAIGHT</b>	Road Grade <b>LEVEL</b>		
	Truck Bus or HazMat <b>NO</b>				
	<b>Vehicle</b>				
		License Plate Number <b>ACW2045</b>	Plate Type <b>AUT - AUTOMOBILE</b>	St <b>WI</b>	Country of Issuance <b>UNITED STATES</b>
	Vehicle Identification Number <b>58ABK1GG3JU112513</b>	Make <b>LEXUS</b>	Year <b>2018</b>	Model <b>ES</b>	
	Color <b>GRY - GRAY</b>	Body Style <b>SD - SEDAN</b>	Bus Use		

9PL01884HQ  
R21-08025

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

UNIT VEHICLE	Initial Contact Point <b>08 - LEFT SIDE REAR</b>	Vehicle Damage <b>08 - LEFT SIDE REAR</b>	
	Extent Of Damage <b>MINOR DAMAGE</b>		
	Towed Due To Damage <b>NOT TOWED</b>	Vehicle Removed By <b>OPERATOR</b>	
	What Driver Was Doing <b>LEGALLY PARKED</b>	Vehicle Factors <b>NOT APPLICABLE</b>	
	Driver Prior Action Other		
UNIT VEHICLE	Driver Actions <b>NO CONTRIBUTING ACTION</b>		
	Owner Name <b>GEORGE LUDWIG JOHNSON (608) 963-5873</b>	Owner Address <b>323 GOLF COURSE RD REEDSBURG, WI 53959 , US</b>	
<b>Sequence Of Events</b>			
UNIT 01	01	Event <b>MOTOR VEH IN TRANSPORT</b>	
	02	Event	
	03	Event	
	04	Event	
<b>Policy Holder</b>			
UNIT	Insurance Company <b>AMERICAN-FAMILY-CONNECT-INS-CO</b>		Individual <b>GEORGE JOHNSON</b>


**Unit Summary**

UNIT 02	Unit Status <b>IN TRANSIT</b>		Vehicle Operating As Classification <b>D CLASS</b>		Unit Type <b>AUTOMOBILE</b>		
	Vehicle Type <b>(SPORT) UTILITY VEHICLE</b>				Operating As Endorsements		
	Total Occs <b>1</b>	Train/Bus # Recorded	Total # Citations Issued <b>2</b>	Total Trailers <b>0</b>	Total HazMat Types <b>0</b>		
	Insurance? <b>YES</b>	Direction Of Travel <b>NOT ON ROADWAY</b>	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit	Total Lanes		
	Most Harmful Event: Collision With <b>PARKED MOTOR VEHICLE</b>		Special Function <b>NO SPECIAL FUNCTION</b>		Emergency Motor Vehicle Use <b>NOT APPLICABLE</b>		
	Traffic Way <b>PARKING LOT OR PRIVATE PROPERTY</b>		Traffic Control <b>NO CONTROL</b>		Traffic Control Inoperative/Missing <b>NO</b>		
	Surface Type <b>BLACKTOP (BITUMINOUS)</b>		Road Curvature <b>STRAIGHT</b>		Road Grade <b>LEVEL</b>		
	Truck Bus or HazMat <b>NO</b>						
	<b>Vehicle</b>						
	UNIT 02	License Plate Number <b>AJH7813</b>		Plate Type <b>AUT - AUTOMOBILE</b>	St <b>WI</b>	Country of Issuance <b>UNITED STATES</b>	
Vehicle Identification Number <b>1FMCU9H66LUA96515</b>		Make <b>FORD</b>	Year <b>2020</b>	Model <b>ESCAPE</b>			
Color <b>SIL - SILVER (ALUMINUM)</b>		Body Style <b>UT - SPORT UTILITY VEHICLE</b>		Bus Use			

9PL01884HQ  
R21-08025

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376



UNIT VEHICLE	Initial Contact Point <b>01 - RIGHT FRONT CORNER</b>		Vehicle Damage <b>01 - RIGHT FRONT CORNER</b>	
	Extent Of Damage <b>MINOR DAMAGE</b>			
	Towed Due To Damage <b>NOT TOWED</b>		Vehicle Removed By <b>OPERATOR</b>	
	What Driver Was Doing <b>PARK MANEUVER</b>		Vehicle Factors	
	Driver Prior Action Other		<b>UNKNOWN</b>	
UNIT VEHICLE	Driver Actions <b>OTHER CONTRIBUTING ACTION</b>			
	Owner Name <b>DANIELLE MARIE SCOTT (608) 963-7851</b>		Owner Address <b>S3127 WAKERLY LN REEDSBURG, WI 53959 , US</b>	
<b>Sequence Of Events</b>				
UNIT VEHICLE	01	Event <b>PARKED MOTOR VEHICLE</b>		
	02	Event		
	03	Event		
	04	Event		
<b>Policy Holder</b>				
UNIT INDIVIDUAL	Insurance Company <b>AMERICAN-FAMILY-CONNECT-INS-CO</b>		Individual <b>DANIELLE SCOTT</b>	
	<b>Individual</b>			
UNIT INDIVIDUAL	Driver <b>DANIELLE MARIE SCOTT (608) 963-7851</b>		Citations Issued <b>2</b>	Sex <b>FEMALE</b>
	Address <b>S3127 WAKERLY LN REEDSBURG, WI 53959 , US</b>		Date of Birth <b>09/18/1972</b>	Race <b>WHITE</b>
			Driver License Number <b>S3001737283805 STATE: WISCONSIN COUNTRY: UNITED STATES</b>	
UNIT INDIVIDUAL	<b>Safety Equipment</b>		On Duty Crash	
	Row <b>01 - FRONT ROW</b>	Seat Position <b>07 - LEFT</b>	Safety Equipment <b>SHOULDER &amp; LAP BELT</b>	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	UNIT INDIVIDUAL	<b>Injury</b>		Injury Severity
		Airbag <b>NON DEPLOYED</b>		
UNIT INDIVIDUAL	Ejected <b>NOT EJECTED</b>		Ejection Path <b>NOT EJECTED/NOT APPLICABLE</b>	Trapped/Extricated <b>NOT TRAPPED</b>
	Medical Transport <b>NOT TRANSPORTED</b>		EMS Agency Identifier	EMS Run #
	Hospital		Date of Death	Time of Death

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

UNIT	INDIVIDUAL	<b>Distracted By</b>		Distracted By Source <b>UNKNOWN</b>				
		Distracted By Action <b>UNKNOWN</b>						
		<b>Non Motorist</b>	Striking Unit #	Location				
			Prior Action					
		Action						
		Action Other				To/From School		
		02	001	<b>Drug &amp; Alcohol</b>		Suspected Alcohol Use <b>NO</b>		
						Suspected Drug Use <b>NO</b>		
				Alcohol Test Given <b>TEST NOT GIVEN</b>	Alcohol Test Type		Alcohol Test Results	
				Drug Test Given <b>TEST NOT GIVEN</b>	Drug Test Type	Drug Test Results		
Drug Type								
Individual Condition <b>NOT OBSERVED</b>								
<b>Violations</b>								
02	01	UTC Number <b>9P800SNQJ9</b>	Issue To? <b>001</b>	Statute Number <b>434-5(h)</b>	Description			
		UTC Number <b>AP275974</b>	Issue To? <b>001</b>	Statute Number <b>346.70(1)</b>	Description <b>FAILURE OF OPERATOR TO NOTIFY POLICE OF ACCIDENT</b>			