

WISCONSIN MOTOR VEHICLE CRASH REPORT

9PL0122XXM

Document Number Override, Primary Crash Document #, Agency Crash Number, Investigating Officer/Deputy C. CALI, Crash Date 08/24/2021, Crash Time 04:48 AM, Date Arrived 08/24/2021, Time Arrived 04:53 AM, Date Notified 08/24/2021, Time Notified 04:48 AM, Total Units 02, Total Injured 00, Total Killed 00, On Emergency, Hit and Run, Lane Closure, Work Zone, Trailer or Towed, Reporting Threshold, Government Property, Active School Zone, School Bus Related NO, Tags, Reportable, DT4000 (STANDARD CRASH), Amended, Secondary Crash

Description

Diagram: Aerial view of N Dewey Ave and High St showing vehicle positions (Unit #1, Unit #2, Trailer) and a north arrow. Reconstruction By, Photos By CALI # 149, Additional Information PHOTOS

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report. AN ENCLOSED TRAILER WAS LEGALLY PARKED IN FRONT OF 529 N. DEWEY AVE. ON THE WEST SIDE OF THE STREET. UNIT # 2 WAS LEGALLY PARKED AND UNOCCUPIED DIRECTLY IN FRONT OF THE TRAILER. UNIT # 1 WAS TRAVELING SOUTHBOUND ON N. DEWEY AVE. THE DRIVER STATED HE BECAME DISTRACTED MOMENTARILY (UNKNOWN HOW DISTRACTED) AND CRASHED INTO THE TRAILER. THE IMPACT OF THE CRASH PUSHED THE TRAILER FORWARD INTO THE REAR OF UNIT # 2, AND PUSHED THE TRAILER OVER THE CURB. THERE WAS SIGNIFICANT DAMAGE TO THE FRONT AND FRONT PASSENGER SIDE OF UNIT # 1. THE DRIVER WAS UNINJURED AND WAS ABLE TO DRIVE THE VEHICLE FROM THE SCENE. UNIT # 2 HAD MINOR DAMAGE TO THE REAR SPARE TIRE AREA AND REAR PASSENGER SIDE. THE TRAILER HAD DAMAGE TO THE REAR AND DAMAGE TO THE FRONT COUPLER AND AXLE. TWO GAS PRESSURE WASHING MACHINES IN THE REAR OF THE TRAILER APPEARED TO HAVE BEEN DAMAGED AS WELL FROM THE ACCIDENT. IT IS UNKNOWN AT THIS TIME IF ADDITIONAL EQUIPMENT IN THE TRAILER WAS DAMAGED. NOTHING FURTHER.

9PL0122XXM

R21-9154

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

Location

ON N DEWEY AVE 117 FT N OF HIGH ST IN THE CITY OF REEDSBURG IN SAUK COUNTY	Latitude <b>43.537329514</b>	Longitude <b>-89.994598257</b>
	X Coordinate <b>258047.140625</b>	Y Coordinate <b>4824844.5</b>
	Structure Type <b>NO STRUCTURE</b>	


Crash Scene

First Harmful Event <b>MOTOR VEH IN TRANSPORT</b>	First Harmful Event Location <b>ON ROADWAY</b>	
Manner of Collision <b>03 - FRONT TO REAR</b>	Light Condition <b>DARK/LIGHTED</b>	
Road Surface Condition(s) <b>DRY</b>	Roadway Factor(s)  <b>NONE</b>	
Environment Factor(s) <b>NONE</b>		
Weather Condition(s) <b>CLEAR</b>		
Animal Type	Relation To Trafficway <b>TRAFFICWAY - ON ROAD</b>	
Crash Classification - Location <b>PUBLIC PROPERTY</b>	Crash Classification - Jurisdiction <b>NO SPECIAL JURISDICTION</b>	
Tribal Land	Access Control <b>FULL CONTROL</b>	Special Study
Within Interchange Area <b>NO</b>	Junction Location <b>NON-JUNCTION</b>	Intersection Type <b>NOT AN INTERSECTION</b>

Unit Summary

<b>UNIT</b>	Unit Status <b>IN TRANSIT</b>	Vehicle Operating As Classification <b>D CLASS</b>		Unit Type <b>AUTOMOBILE</b>	
	Vehicle Type <b>PASSENGER CAR</b>	Operating As Endorsements			
	Total Occs <b>1</b>	Train/Bus # Recorded	Total # Citations Issued <b>0</b>	Total Trailers <b>0</b>	Total HazMat Types <b>0</b>
	Insurance? <b>YES</b>	Direction Of Travel <b>SOUTHBOUND</b>	<input type="checkbox"/> <b>Pre CrashTire Mark</b>	Speed Limit <b>25</b>	Total Lanes <b>2</b>
	Most Harmful Event: Collision With <b>OTHER OBJECT - NOT FIXED</b>	Special Function <b>NO SPECIAL FUNCTION</b>		Emergency Motor Vehicle Use <b>NOT APPLICABLE</b>	
	Traffic Way <b>TWO-WAY, NOT DIVIDED</b>	Traffic Control <b>NO CONTROL</b>		Traffic Control Inoperative/Missing <b>NO</b>	
	Surface Type <b>BLACKTOP (BITUMINOUS)</b>	Road Curvature <b>STRAIGHT</b>		Road Grade <b>LEVEL</b>	
	Truck Bus or HazMat <b>NO</b>				

<b>UNIT</b>	<b>Vehicle</b>				
	<b>01</b>	License Plate Number <b>255BUC</b>	Plate Type <b>AUT - AUTOMOBILE</b>	St <b>WI</b>	Country of Issuance <b>UNITED STATES</b>
		Vehicle Identification Number <b>2G1WL52M9W9306927</b>	Make <b>CHEVROLET</b>	Year <b>1998</b>	Model <b>LUMINA/LS</b>
	<b>VEHICLE</b>	Color <b>TAN - TAN</b>	Body Style <b>4D - 4DR</b>		Bus Use
		Initial Contact Point <b>01 - RIGHT FRONT CORNER</b>	Vehicle Damage <b>01 - RIGHT FRONT CORNER, 12 - FRONT</b>		
Extent Of Damage <b>FUNCTIONAL DAMAGE</b>					



9PL0122XXM

R21-9154

# WISCONSIN MOTOR VEHICLE CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

UNIT VEHICLE	Towed Due To Damage <b>NOT TOWED</b>		Vehicle Removed By <b>OPERATOR</b>	
	What Driver Was Doing <b>GOING STRAIGHT</b>		Vehicle Factors	
	Driver Prior Action Other		<b>NOT APPLICABLE</b>	
	Driver Actions <b>FAILED TO KEEP IN DESIGNATED LANE</b>			
01	Owner Name <b>KIM P SCHMIDTKE (608) 253-4688</b>		Owner Address <b>W14489 STATE ROAD 16 WISCONSIN DELLS, WI 53965 , US</b>	
	<b>Sequence Of Events</b>			
01	01	Event <b>MOTOR VEH IN TRANSPORT</b>		
	02	Event <b>OTHER OBJECT - NOT FIXED</b>		
	03	Event		
	04	Event		
UNIT	<b>Policy Holder</b>			
	Insurance Company <b>STATE-FARM-MUTUAL-AUTOMOBILE-INS-CO</b>		Individual <b>KIM SCHMIDTKE</b>	
UNIT INDIVIDUAL	<b>Individual</b>			
	Driver <b>KIM P SCHMIDTKE (608) 253-4688</b>		Citations Issued <b>0</b>	Sex <b>MALE</b>
	Address <b>W14489 STATE ROAD 16 WISCONSIN DELLS, WI 53965 , US</b>		Date of Birth <b>06/08/1955</b>	Race <b>WHITE</b>
			Driver License Number <b>S5325155520804 STATE: WISCONSIN COUNTRY: UNITED STATES</b>	
01	<b>Safety Equipment</b>		On Duty Crash	
			Safety Equipment	
	Row <b>01 - FRONT ROW</b>	Seat Position <b>07 - LEFT</b>	<b>SHOULDER &amp; LAP BELT</b>	
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
	<b>Injury</b>		Injury Severity <b>NO APPARENT INJURY</b>	Airbag <b>NON DEPLOYED</b>
Ejected <b>NOT EJECTED</b>		Ejection Path <b>NOT EJECTED/NOT APPLICABLE</b>		Trapped/Extricated <b>NOT TRAPPED</b>
Medical Transport <b>NOT TRANSPORTED</b>		EMS Agency Identifier		EMS Run #
Hospital		Date of Death		Time of Death
<b>Distracted By</b>		Distracted By Source <b>UNKNOWN</b>		
Distracted By Action <b>UNKNOWN</b>				


WISCONSIN MOTOR VEHICLE  
CRASH REPORT

UNIT           01  001	<b>Non Motorist</b>		Striking Unit #	Location	
	Prior Action				
	Action				
	Action Other			To/From School	
	<b>Drug &amp; Alcohol</b>		Suspected Alcohol Use <b>NO</b>	Suspected Drug Use <b>NO</b>	
	Alcohol Test Given <b>TEST NOT GIVEN</b>		Alcohol Test Type	Alcohol Test Results	
	Drug Test Given <b>TEST NOT GIVEN</b>		Drug Test Type	Drug Test Results	
	Drug Type				
	Individual Condition <b>APPEARED NORMAL</b>				

**Unit Summary**

UNIT           02           02	Unit Status <b>LEGALLY PARKED</b>		Vehicle Operating As Classification <b>D CLASS</b>		Unit Type <b>AUTOMOBILE</b>	
	Vehicle Type <b>(SPORT) UTILITY VEHICLE</b>				Operating As Endorsements	
	Total Occs <b>0</b>	Train/Bus # Recorded	Total # Citations Issued <b>0</b>	Total Trailers <b>0</b>	Total HazMat Types <b>0</b>	
	Insurance? <b>YES</b>	Direction Of Travel <b>SOUTHBOUND</b>	<input type="checkbox"/> <b>Pre Crash Tire Mark</b>	Speed Limit <b>25</b>	Total Lanes <b>2</b>	
	Most Harmful Event: Collision With <b>MOTOR VEH IN TRANSPORT</b>		Special Function <b>NO SPECIAL FUNCTION</b>		Emergency Motor Vehicle Use <b>NOT APPLICABLE</b>	
	Traffic Way <b>TWO-WAY, NOT DIVIDED</b>		Traffic Control <b>NO CONTROL</b>		Traffic Control Inoperative/Missing <b>NO</b>	
	Surface Type <b>BLACKTOP (BITUMINOUS)</b>		Road Curvature <b>STRAIGHT</b>		Road Grade <b>LEVEL</b>	
	Truck Bus or HazMat <b>NO</b>					

UNIT           02           02	<b>Vehicle</b>					
	License Plate Number <b>AKY6856</b>		Plate Type <b>AUT - AUTOMOBILE</b>	St <b>WI</b>	Country of Issuance <b>UNITED STATES</b>	
	Vehicle Identification Number <b>JHLRD184X1C027069</b>		Make <b>HONDA</b>	Year <b>2001</b>	Model <b>CR-V</b>	
	Color <b>BLU - BLUE</b>		Body Style <b>UT - SPORT UTILITY VEHICLE</b>		Bus Use	
	Initial Contact Point <b>06 - REAR</b>		Vehicle Damage			
	Extent Of Damage <b>MINOR DAMAGE</b>		<b>05 - RIGHT REAR CORNER, 06 - REAR</b>			
Towed Due To Damage <b>NOT TOWED</b>		Vehicle Removed By <b>OPERATOR</b>				



9PL0122XXM

R21-9154

# WISCONSIN MOTOR VEHICLE CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

<b>UNIT</b>	<b>VEHICLE</b>	What Driver Was Doing <b>LEGALLY PARKED</b>	Vehicle Factors			
		Driver Prior Action Other	<b>NOT APPLICABLE</b>			
		Driver Actions				
		Owner Name <b>LAURA J WHEELER</b> <b>(608) 697-7055</b>	Owner Address <b>529 N DEWEY AVE # 4</b> <b>REEDSBURG, WI 53959 , US</b>			
<b>UNIT</b>	<b>02</b>	<b>Sequence Of Events</b>				
		<b>01</b>	Event <b>MOTOR VEH IN TRANSPORT</b>			
		<b>02</b>	Event			
		<b>03</b>	Event			
		<b>04</b>	Event			
<b>UNIT</b>	<b>02</b>	<b>Policy Holder</b>				
		Insurance Company <b>HOFMEISTER INSURANCE AGENCY</b>	Individual <b>LAURA WHEELER</b>			
<b>Property Owner</b>						
<b>PROP OWNER</b>	<b>01</b>	Individual <b>JOHNIE V WHEELER</b> <b>(608) 697-7055</b>	Address <b>529 N DEWEY AVE # 4</b> <b>REEDSBURG, WI 53959 , US</b>			
		<b>Fixed Objects Struck</b>				
<b>UNIT</b>	<b>02</b>	<b>01</b>	Striking Unit <b>01</b>	Struck Object <b>OTHER OBJECT - NOT FIXED</b>	Structure Number	Damage Tag Number
		<b>02</b>	Striking Unit <b>01</b>	Struck Object <b>OTHER OBJECT - NOT FIXED</b>	Structure Number	Damage Tag Number