

9PL01884HV  
CASE#R21-09729

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

9PL01884HV

Document Number Override		Primary Crash Document #		Agency Crash Number <b>CASE#R21-09729</b>		Investigating Officer/Deputy <b>T. KNUTH</b>	
Crash Date <b>09/09/2021</b>		Crash Time <b>07:58 AM</b>		Date Arrived <b>09/09/2021</b>		Time Arrived <b>08:06 AM</b>	
Date Notified <b>09/09/2021</b>		Time Notified <b>07:58 AM</b>		Total Units <b>02</b>		Total Injured <b>01</b>	Total Killed <b>00</b>
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure		<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related <b>NO</b>		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type <b>DT4000 (STANDARD CRASH)</b>				<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

Diagram		Reconstruction By	
		Photos By <b>T. KNUTH #130</b>	
		Additional Information <b>PHOTOS</b>	

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT 2 WAS LEGALLY PARKED ON PLUM ST JUST WEST OF S OAK ST ON THE SOUTH SIDE OF THE STREET FACING EAST. UNIT 1 HAD JUST TURNED ONTO PLUM ST FROM S. WILLOW ST AND BEGAN DRIVING EAST ON PLUM ST. THE DRIVER OF UNIT 1 WAS BLINDED BY THE BRIGHT SUNLIGHT AND STRUCK THE REAR OF UNIT 2. UNIT 1 ESTIMATED SHE WAS GONG 15-20 MPH WHEN SHE STRUCK UNIT 2. I DID CONFIRM WHILE I WAS ON SCENE THAT THE SUN WAS EXTREMELY BRIGHT AND COULD HAVE EASILY AFFECTED THE VISION OF THE OPERATOR OF UNIT 1. OPERATOR OF UNIT 1 SAID HER LEFT SHOULDER HURT SLIGHTLY FROM THE CRASH. UNIT 1 SUSTAINED DISABLING DAMAGE AND WAS TOWED FROM THE SCENE. I WAS EVENTUALLY ABLE TO MAKE PHONE CONTACT WITH THE OWNER OF UNIT 2. REGISTRATION OF UNIT 2 HAD EXPIRED IN 2019 AND OWNER SAID HE HAD JUST PURCHASED THE VEHICLE ABOUT A WEEK AGO AND HAD NOT PUT THE VEHICLE REGISTRATION IN HIS NAME BUT WAS PLANNING ON DOING SO ALONG WITH REGISTERING THE VEHICLE. OWNER OF UNIT 2 SAID HE DID NOT WANT TO MAKE CONTACT WITH ME IN PERSON BECAUSE HE HAD A WARRANT FOR HIS ARREST BUT I WAS ABLE TO OBTAIN THE NEEDED INFORMATION TO COMPLETE THIS CRASH REPORT. NOTHING FURTHER.

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

Location

ON PLUM ST 154 FT W OF S OAK ST IN THE CITY OF REEDSBURG IN SAUK COUNTY	Latitude <b>43.530418878</b>	Longitude <b>-89.998863451</b>
	X Coordinate <b>257674.8125</b>	Y Coordinate <b>4824089.5</b>
	Structure Type	

Crash Scene

First Harmful Event <b>PARKED MOTOR VEHICLE</b>	First Harmful Event Location <b>ON ROADWAY</b>	
Manner of Collision <b>03 - FRONT TO REAR</b>	Light Condition <b>DAYLIGHT</b>	
Road Surface Condition(s) <b>DRY</b>	Roadway Factor(s)  <b>NONE</b>	
Environment Factor(s) <b>GLARE</b>		
Weather Condition(s) <b>CLEAR</b>		
Animal Type	Relation To Trafficway <b>TRAFFICWAY - ON ROAD</b>	
Crash Classification - Location <b>PUBLIC PROPERTY</b>	Crash Classification - Jurisdiction <b>NO SPECIAL JURISDICTION</b>	
Tribal Land	Access Control <b>NO CONTROL</b>	Special Study
Within Interchange Area <b>NO</b>	Junction Location <b>NON-JUNCTION</b>	Intersection Type <b>NOT AN INTERSECTION</b>

Unit Summary

<b>UNIT</b>	Unit Status <b>IN TRANSIT</b>	Vehicle Operating As Classification <b>D CLASS</b>	Unit Type <b>AUTOMOBILE</b>		
	Vehicle Type <b>(SPORT) UTILITY VEHICLE</b>	Operating As Endorsements			
	Total Occs <b>2</b>	Train/Bus # Recorded	Total # Citations Issued <b>0</b>	Total Trailers <b>0</b>	Total HazMat Types <b>0</b>
	Insurance? <b>YES</b>	Direction Of Travel <b>EASTBOUND</b>	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit <b>25</b>	Total Lanes <b>2</b>
	Most Harmful Event: Collision With <b>PARKED MOTOR VEHICLE</b>	Special Function <b>NO SPECIAL FUNCTION</b>		Emergency Motor Vehicle Use <b>NOT APPLICABLE</b>	
	Traffic Way <b>TWO-WAY, NOT DIVIDED</b>	Traffic Control <b>NO CONTROL</b>		Traffic Control Inoperative/Missing <b>NO</b>	
	Surface Type <b>BLACKTOP (BITUMINOUS)</b>	Road Curvature <b>STRAIGHT</b>		Road Grade <b>UPHILL</b>	
	Truck Bus or HazMat <b>NO</b>				

Vehicle

<b>UNIT</b>	<b>VEHICLE</b>	<b>01</b>	License Plate Number <b>AHM2882</b>	Plate Type <b>AUT - AUTOMOBILE</b>	St <b>WI</b>	Country of Issuance <b>UNITED STATES</b>	
			Vehicle Identification Number <b>2GNALAEK6F6209729</b>	Make <b>CHEVROLET</b>	Year <b>2015</b>	Model <b>EQUINOX</b>	
			Color <b>BLU - BLUE</b>	Body Style <b>UT - SPORT UTILITY VEHICLE</b>		Bus Use	
			Initial Contact Point <b>01 - RIGHT FRONT CORNER</b>	Vehicle Damage <b>01 - RIGHT FRONT CORNER, 02 - RIGHT SIDE FRONT, 12 - FRONT</b>			
			Extent Of Damage <b>DISABLING DAMAGE</b>				



WISCONSIN MOTOR VEHICLE  
CRASH REPORT

UNIT	Towed Due To Damage <b>TOWED DUE TO DISABLING DAMAGE</b>		Vehicle Removed By <b>STEVE'S AUTO</b>		
	What Driver Was Doing <b>GOING STRAIGHT</b>		Vehicle Factors		
	Driver Prior Action Other		<b>NOT APPLICABLE</b>		
	Driver Actions <b>FAILED TO KEEP IN DESIGNATED LANE</b>				
01	01	Owner Name <b>SARAH L SINGLETARY (608) 630-0437</b>		Owner Address <b>235 S WILLOW ST REEDSBURG, WI 53959 , US</b>	
		<b>Sequence Of Events</b>			
UNIT	01	Event <b>PARKED MOTOR VEHICLE</b>			
		Event			
		Event			
		Event			
UNIT	01	<b>Policy Holder</b>			
		Insurance Company <b>STATE-FARM-GENERAL-INS-CO</b>	Individual <b>SARAH SINGLETARY</b>		
UNIT	01	<b>Individual</b>			
		Driver <b>SARAH L SINGLETARY (608) 630-0437</b>	Citations Issued <b>0</b>	Sex <b>FEMALE</b>	
		Date of Birth <b>05/06/1976</b>		Race <b>WHITE</b>	
		Address <b>235 S WILLOW ST REEDSBURG, WI 53959 , US</b>		Driver License Number <b>S5247927666600 STATE: WISCONSIN COUNTRY: UNITED STATES</b>	
01	001	<b>Safety Equipment</b>		On Duty Crash	
				Safety Equipment	
		Row <b>01 - FRONT ROW</b>	Seat Position <b>07 - LEFT</b>	<b>SHOULDER &amp; LAP BELT</b>	
		Helmet Use		Helmet Compliance	
Eye Protection		Tint Compliance			
<b>Injury</b>		Injury Severity <b>POSSIBLE INJURY</b>	Airbag <b>NON DEPLOYED</b>		
Ejected <b>NOT EJECTED</b>		Ejection Path <b>NOT EJECTED/NOT APPLICABLE</b>		Trapped/Extricated <b>NOT TRAPPED</b>	
Medical Transport <b>NOT TRANSPORTED</b>		EMS Agency Identifier		EMS Run #	
Hospital		Date of Death		Time of Death	
<b>Distracted By</b>		Distracted By Source <b>NOT APPLICABLE (NOT DISTRACTED)</b>			
<b>Distracted By Action</b>		<b>NOT DISTRACTED</b>			

WISCONSIN MOTOR VEHICLE  
CRASH REPORT

UNIT	INDIVIDUAL	<b>Non Motorist</b>		Striking Unit #	Location		
		Prior Action					
		Action					
		Action Other					
		To/From School					
		<b>Drug &amp; Alcohol</b>		Suspected Alcohol Use <b>NO</b>	Suspected Drug Use <b>NO</b>		
		Alcohol Test Given <b>TEST NOT GIVEN</b>		Alcohol Test Type		Alcohol Test Results	
		Drug Test Given <b>TEST NOT GIVEN</b>		Drug Test Type		Drug Test Results	
		Drug Type					
		Individual Condition <b>APPEARED NORMAL</b>					
UNIT	INDIVIDUAL	<b>Individual</b>					
		Passenger <b>KEIRA R GRASSL (608) 630-0437</b>		Citations Issued <b>0</b>	Sex <b>FEMALE</b>		
				Date of Birth <b>08/29/2015</b>	Race <b>WHITE</b>		
		Address <b>235 S WILLOW ST REEDSBURG, WI 53959 , US</b>		Driver License Number			
		<b>Safety Equipment</b>		On Duty Crash	Safety Equipment		
		Row <b>02 - SECOND ROW</b>		Seat Position <b>07 - LEFT</b>	<b>BOOSTER SEAT</b>		
		Helmet Use		Helmet Compliance			
		Eye Protection		Tint Compliance			
		UNIT	INDIVIDUAL	<b>Injury</b>		Injury Severity <b>NO APPARENT INJURY</b>	Airbag <b>NON DEPLOYED</b>
				Ejected <b>NOT EJECTED</b>		Ejection Path <b>NOT EJECTED/NOT APPLICABLE</b>	
Medical Transport <b>NOT TRANSPORTED</b>				EMS Agency Identifier		EMS Run #	
Hospital				Date of Death		Time of Death	
<b>Distracted By</b>				Distracted By Source			
Distracted By Action							
<b>Non Motorist</b>				Striking Unit #	Location		

UNIT	INDIVIDUAL	Prior Action			
		Action			
		Action Other	To/From School		
	01	002	<b>Drug &amp; Alcohol</b>		
			Suspected Alcohol Use	Suspected Drug Use	
			NO	NO	
			Alcohol Test Given	Alcohol Test Type	Alcohol Test Results
			TEST NOT GIVEN		
			Drug Test Given	Drug Test Type	Drug Test Results
			TEST NOT GIVEN		
Drug Type					
Individual Condition		APPEARED NORMAL			

**Unit Summary**

UNIT	02	Unit Status	Vehicle Operating As Classification	Unit Type		
		LEGALLY PARKED	D CLASS	TRUCK		
		Vehicle Type	Operating As Endorsements			
		UTILITY TRUCK/PICKUP TRUCK				
		Total Occs	Train/Bus # Recorded	Total # Citations Issued	Total Trailers	Total HazMat Types
		0		0	0	0
		Insurance?	Direction Of Travel	<input type="checkbox"/> Pre Crash Tire Mark	Speed Limit	Total Lanes
		NO	EASTBOUND		25	2
		Most Harmful Event: Collision With	Special Function	Emergency Motor Vehicle Use		
		MOTOR VEH IN TRANSPORT	NO SPECIAL FUNCTION	NOT APPLICABLE		
Traffic Way	Traffic Control	Traffic Control Inoperative/Missing				
TWO-WAY, NOT DIVIDED	NO CONTROL	NO				
Surface Type	Road Curvature	Road Grade				
BLACKTOP (BITUMINOUS)	STRAIGHT	UPHILL				
Truck Bus or HazMat	NO					

**Vehicle**

UNIT	VEHICLE	02	02	License Plate Number	Plate Type	St	Country of Issuance
				PE3858	LTK - LIGHT TRUCK	WI	UNITED STATES
				Vehicle Identification Number	Make	Year	Model
				1FTDF1766VLB04126	FORD	1997	F150
				Color	Body Style	Bus Use	
				WHI - WHITE	PK - PICKUP		
				Initial Contact Point	Vehicle Damage		
				07 - LEFT REAR CORNER	07 - LEFT REAR CORNER		
Extent Of Damage	Vehicle Removed By						
MINOR DAMAGE	OWNER						
Towed Due To Damage	What Driver Was Doing						
NOT TOWED	LEGALLY PARKED						

9PL01884HV  
CASE#R21-09729

# WISCONSIN MOTOR VEHICLE CRASH REPORT

REEDSBURG POLICE DEPARTMENT  
200 SOUTH PARK STREET  
REEDSBURG, WI 53959  
(608) 524-2376

UNIT VEHICLE	Vehicle Factors	
	Driver Prior Action Other	NOT APPLICABLE
	Driver Actions <b>NO CONTRIBUTING ACTION</b>	
02	Owner Name <b>SCOTT E RUTTER (608) 477-3721</b>	Owner Address <b>608 VINE ST BARABOO, WI 53913 , US</b>
	<b>Sequence Of Events</b>	
01	Event <b>MOTOR VEH IN TRANSPORT</b>	
02	Event	
03	Event	
04	Event	