

9PL009V8VW
R20-10716

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

9PL009V8VW

Document Number Override		Primary Crash Document #		Agency Crash Number		Investigating Officer/Deputy M. EBERLE	
Crash Date 09/03/2020		Crash Time 11:00 AM		Date Arrived 09/03/2020		Time Arrived 11:15 AM	
Date Notified 09/03/2020		Time Notified 11:15 AM		Total Units 02		Total Injured 01	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure	<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	<input type="checkbox"/> Reporting Threshold	
<input type="checkbox"/> Government Property		<input type="checkbox"/> Active School Zone		School Bus Related NO		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (STANDARD CRASH)				<input type="checkbox"/> Amended	<input type="checkbox"/> Secondary Crash

Description

Diagram		Reconstruction By
		Photos By SGT. EBERLE
		Additional Information PHOTOS

I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.

UNIT #2 WAS STOPPING IN LANE OF TRAFFIC TO PERFORM LEGAL TURN SOUTH OR LEFT ON TO S. GROVE ST WITH DIRECTIONAL ACTIVATED. UNIT #1 WAS ALSO TRAVELING WESTBOUND. UNIT #1 OPERATOR STATED HE LOOKED DOWN AT HIS CELLPHONE, WHEN HE LOOKED UP HE OBSERVED VEHICLE STOPPED IN TRAFFIC PERFORMING A TURN. UNIT #1 WAS FOLLOWING TOO CLOSELY AND WAS UNABLE TO STOP IN TIME, STRIKING UNIT #2. OPERATOR OF UNIT #2 WAS TRANSPORTED TO MEDICAL FACILITY VIA REEDSBURG AMBULANCE FOR RIB AND HEAD PAINS.

9PL009V8VW
R20-10716

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

Location

ON MAIN ST/ STH23 WB 84 FT E OF N GROVE ST IN THE CITY OF REEDSBURG IN SAUK COUNTY	Latitude 43.532449013	Longitude -89.996134194
	X Coordinate 257903.484375	Y Coordinate 4824307
	Structure Type	

Crash Scene

First Harmful Event MOTOR VEH IN TRANSPORT	First Harmful Event Location ON ROADWAY	
Manner of Collision 03 - FRONT TO REAR	Light Condition DAYLIGHT	
Road Surface Condition(s) DRY	Roadway Factor(s) NONE	
Environment Factor(s) NONE		
Weather Condition(s) CLEAR		
Animal Type	Relation To Trafficway TRAFFICWAY - ON ROAD	
Crash Classification - Location PUBLIC PROPERTY	Crash Classification - Jurisdiction NO SPECIAL JURISDICTION	
Tribal Land	Access Control NO CONTROL	Special Study
Within Interchange Area NO	Junction Location INTERSECTION	Intersection Type FOUR-WAY INTERSECTION

Unit Summary

UNIT	Unit Status IN TRANSIT	Vehicle Operating As Classification D CLASS	Unit Type AUTOMOBILE		
	Vehicle Type (SPORT) UTILITY VEHICLE	Operating As Endorsements			
	Total Occs 1	Train/Bus # Recorded	Total # Citations Issued 1	Total Trailers 0	Total HazMat Types 0
	Insurance? YES	Direction Of Travel WESTBOUND	<input type="checkbox"/> Pre CrashTire Mark	Speed Limit 25	Total Lanes 4
	Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT	Special Function NO SPECIAL FUNCTION		Emergency Motor Vehicle Use NOT APPLICABLE	
	Traffic Way TWO-WAY, NOT DIVIDED	Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type BLACKTOP (BITUMINOUS)	Road Curvature STRAIGHT		Road Grade LEVEL	
	Truck Bus or HazMat NO				

UNIT	VEHICLE	Vehicle			
		License Plate Number 152ZPV	Plate Type AUT - AUTOMOBILE	St WI	Country of Issuance UNITED STATES
		Vehicle Identification Number 2GNAXSEV6J6300383	Make CHEVROLET	Year 2018	Model EQUINOX
		Color WHI - WHITE	Body Style UT - SPORT UTILITY VEHICLE		Bus Use NOT A BUS
		Initial Contact Point 11 - LEFT FRONT CORNER	Vehicle Damage 11 - LEFT FRONT CORNER, 12 - FRONT		
Extent Of Damage FUNCTIONAL DAMAGE					

9PL009V8VW
R20-10716

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

UNIT VEHICLE	Towed Due To Damage NOT TOWED		Vehicle Removed By OPERATOR	
	What Driver Was Doing GOING STRAIGHT		Vehicle Factors	
	Driver Prior Action Other		NOT APPLICABLE	
	Driver Actions FOLLOWING TOO CLOSE			
01	01	Owner Name ALEXANDER ANDRE DEJESUS (608) 963-6033		Owner Address 1140 19TH ST APT 13 REEDSBURG, WI 53959 , US
Sequence Of Events				
	01	Event MOTOR VEH IN TRANSPORT		
	02	Event MOTOR VEH IN TRANSPORT		
	03	Event MOTOR VEH IN TRANSPORT		
	04	Event		
UNIT	Policy Holder			
	Insurance Company PROGRESSIVE-CASUALTY-INS-CO		Individual ALEXANDER DEJESUS	
UNIT INDIVIDUAL	Individual			
	Driver ALEXANDER ANDRE DEJESUS (608) 963-6033		Citations Issued 0	Sex MALE
	Date of Birth 01/31/1998		Race WHITE	
	Address 1140 19TH ST APT 13 REEDSBURG, WI 53959 , US		Driver License Number D2220019803109 STATE: WISCONSIN COUNTRY: UNITED STATES	
UNIT 001	Safety Equipment		On Duty Crash	
	Safety Equipment		SHOULDER & LAP BELT	
	Row 01 - FRONT ROW	Seat Position 07 - LEFT		
	Helmet Use		Helmet Compliance	
	Eye Protection		Tint Compliance	
UNIT 001	Injury		Injury Severity NO APPARENT INJURY	
	Airbag		DEPLOYED-FRONT	
	Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE		Trapped/Extricated NOT TRAPPED
	Medical Transport NOT TRANSPORTED		EMS Agency Identifier	EMS Run #
	Hospital		Date of Death	Time of Death
	Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)	
Distracted By Action OTHER ACTION (LOOKING AWAY FROM TASK ETC)				

9PL009V8VW
R20-10716

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

UNIT	INDIVIDUAL	Non Motorist		Striking Unit #	Location	
		Prior Action				
		Action				
	Action Other				To/From School	
	Drug & Alcohol		Suspected Alcohol Use NO	Suspected Drug Use NO		
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type	Alcohol Test Results		
	Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results		
	Drug Type					
	Individual Condition APPEARED NORMAL					
	Violations					
01	UTC Number AL852732	Issue To? V01	Statute Number 346.14(1m)	Description AUTOMOBILE FOLLOWING TOO CLOSELY		

Unit Summary

UNIT	02	Unit Status IN TRANSIT		Vehicle Operating As Classification D CLASS		Unit Type AUTOMOBILE							
		Vehicle Type PASSENGER CAR				Operating As Endorsements							
		Total Occs 1		Train/Bus # Recorded		Total # Citations Issued 0		Total Trailers 0		Total HazMat Types 0			
		Insurance? YES		Direction Of Travel WESTBOUND		<input type="checkbox"/> Pre Crash Tire Mark		Speed Limit 25		Total Lanes 4			
		Most Harmful Event: Collision With MOTOR VEH IN TRANSPORT				Special Function NO SPECIAL FUNCTION				Emergency Motor Vehicle Use NOT APPLICABLE			
		Traffic Way TWO-WAY, NOT DIVIDED				Traffic Control NO CONTROL				Traffic Control Inoperative/Missing NO			
		Surface Type BLACKTOP (BITUMINOUS)				Road Curvature STRAIGHT				Road Grade LEVEL			
		Truck Bus or HazMat NO											

02	02	Vehicle							
		License Plate Number 19131DS		Plate Type AUT - AUTOMOBILE		St WI		Country of Issuance UNITED STATES	
		Vehicle Identification Number 1NXBU40E79Z133811		Make TOYOTA		Year 2009		Model COROLLA	
		Color TAN - TAN		Body Style SD - SEDAN				Bus Use	
		Initial Contact Point 06 - REAR							

9PL009V8VW
R20-10716

WISCONSIN MOTOR VEHICLE
CRASH REPORT

REEDSBURG POLICE DEPARTMENT
200 SOUTH PARK STREET
REEDSBURG, WI 53959
(608) 524-2376

UNIT VEHICLE	Vehicle Damage	
	Extent Of Damage FUNCTIONAL DAMAGE	05 - RIGHT REAR CORNER, 06 - REAR, 07 - LEFT REAR CORNER
	Towed Due To Damage NOT TOWED	Vehicle Removed By OPERATOR
	What Driver Was Doing SLOW/STOPPING	Vehicle Factors
UNIT VEHICLE	Driver Prior Action Other	NOT APPLICABLE
	Driver Actions NO CONTRIBUTING ACTION	
02 02	Owner Name LYNN ADELE CAPENER	Owner Address 227 FIELDSTONE DR # 109 WISCONSIN DELLS, WI 53965 , US
	Sequence Of Events	
01 02 03 04	Event MOTOR VEH IN TRANSPORT	
	Event MOTOR VEH IN TRANSPORT	
	Event MOTOR VEH IN TRANSPORT	
	Event	
UNIT	Policy Holder	
	Insurance Company UNITED FIRE AND CASUALTY	Individual LYNN CAPENER
UNIT INDIVIDUAL	Individual	
	Driver LYNN ADELE CAPENER	Citations Issued 0
		Sex FEMALE
		Date of Birth 11/07/1949
	Race WHITE	
	Address 227 FIELDSTONE DR # 109 WISCONSIN DELLS, WI 53965 , US	Driver License Number C1565214990702 STATE: WISCONSIN COUNTRY: UNITED STATES
02 002	Safety Equipment	
	On Duty Crash	Safety Equipment
	Row 01 - FRONT ROW	Seat Position 07 - LEFT
	SHOULDER & LAP BELT	
	Helmet Use	Helmet Compliance
	Eye Protection	Tint Compliance
Injury	Injury Severity SUSPECTED MINOR INJURY	Airbag NON DEPLOYED
	Ejected NOT EJECTED	Ejection Path NOT EJECTED/NOT APPLICABLE
	Trapped/Extricated NOT TRAPPED	
	Medical Transport EMS GROUND	EMS Agency Identifier 511
	EMS Run #	
	Hospital REEDSBURG AREA MED CTR	Date of Death
	Time of Death	

WISCONSIN MOTOR VEHICLE
CRASH REPORT

UNIT	Distracted By		Distracted By Source NOT APPLICABLE (NOT DISTRACTED)		
	Distracted By Action NOT DISTRACTED				
	Non Motorist		Striking Unit #	Location	
	Prior Action				
	Action				
	Action Other				To/From School
	Drug & Alcohol		Suspected Alcohol Use NO		Suspected Drug Use NO
	Alcohol Test Given TEST NOT GIVEN		Alcohol Test Type		Alcohol Test Results
	Drug Test Given TEST NOT GIVEN		Drug Test Type	Drug Test Results	
	Drug Type				
02	002	Individual Condition			
		APPEARED NORMAL			